

DATE RECEIVED 9-3-2024

RECEIVED BY MKC

CLAIM NO. 10-24

CITY OF SHEBOYGAN NOTICE OF DAMAGE OR INJURY

INSTRUCTIONS: TYPE OR PRINT IN BLACK INK

- 1. Notice of death, injury to persons or to property must be filed not later than 120 days after the occurrence.
- 2. Attach and sign additional supportive sheets, if necessary.
- 3. This notice form must be signed and filed with the Office of the City Clerk.

**4. TWO ESTIMATES MUST BE ATTACHED IF YOU ARE CLAIMING DAMAGE TO A VEHICLE.**

- 1. Name of Claimant: Jenny Stephen-Pierce
- 2. Home address of Claimant: 1822 S 17<sup>th</sup> Sheboygan, WI
- 3. Home phone number: cell- 920-254-2542
- 4. Business address and phone number of Claimant: \_\_\_\_\_

5. When did damage or injury occur? (date, time of day) August 16, 2024 between 2:00-2:30pm

6. Where did damage or injury occur? (give full description) Car was parked in front of 1716 Elm Ave. During a storm a tree on city property fell from 1715 Elm Ave onto the vehicle.

7. How did damage or injury occur? (give full description) Damage occurred when the tree fell on August 16, 2024

8. If the basis of liability is alleged to be an act or omission of a City officer or employee, complete the following:

(a) Name of such officer or employee, if known: \_\_\_\_\_

(b) Claimant's statement of the basis of such liability: \_\_\_\_\_

9. If the basis of liability is alleged to be a dangerous condition of public property, complete the following:

(a) Public property alleged to be dangerous: Tree was marked to come down. This particular tree was damaged in June from a storm.

(b) Claimant's statement of basis for such liability: \_\_\_\_\_

Several ~~area~~ neighbors have been asking the city for the last <sup>couple</sup> years to cut down the tree.

10. Give a description of the injury, property damage or loss, so far as is known at this time. (If there were no injuries, state "NO INJURIES").

NO Injuries

11. Name and address of any other person injured: \_\_\_\_\_

12. Damage estimate: (You are not bound by the amounts provided here.)

Auto: \$ 2 estimates included see sheets  
 Property: \$ \_\_\_\_\_ 7,114.31  
 Personal injury: \$ \_\_\_\_\_  
 Other: (Specify below) \$ \_\_\_\_\_  
**TOTAL** \$ 7,114.31

Damaged vehicle (if applicable)


Make: CHEVY Model: Equinox Year: 2008 Mileage: 58,724

Names and addresses of witnesses, doctors and hospitals: \_\_\_\_\_

ALAN Heusterberg - 1715 Elm Ave  
PAT MARTIN 1719 Elm Ave

FOR ALL ACCIDENT NOTICES, COMPLETE THE FOLLOWING DIAGRAM IN DETAIL. BE SURE TO INCLUDE NAMES OF ALL STREETS, HOUSE NUMBERS, LOCATION OF VEHICLES, INDICATING WHICH IS CITY VEHICLE (IF APPLICABLE), WHICH IS CLAIMANT VEHICLE, LOCATION OF INDIVIDUALS, ETC.

NOTE: If diagrams below do not fit the situation, attach proper diagram and sign.



SIGNATURE OF CLAIMANT Jenny Stephen-Petrie DATE 9-3-24

17th Street

↓ 1715  
Eim  
Ave



Eim Ave

187



DATE RECEIVED \_\_\_\_\_

RECEIVED BY \_\_\_\_\_

CLAIM NO. \_\_\_\_\_

CLAIM

Claimant's Name: Jenny Stephen-Pierce  
 Claimant's Address: 1822 S 17  
Sheboygan, WI  
 Claimant's Phone No. 920-254-2542

Auto	\$	<u>7,114.31</u>
Property	\$	_____
Personal Injury	\$	_____
Other (Specify below)	\$	_____
<b>TOTAL</b>		\$ <u>7,114.31</u>

PLEASE INCLUDE COPIES OF ALL BILLS, INVOICES, ESTIMATES, ETC.


WARNING: IT IS A CRIMINAL OFFENSE TO FILE A FALSE CLAIM.  
(WISCONSIN STATUTES 943.395)

The undersigned hereby makes a claim against the City of Sheboygan arising out of the circumstances described in the Notice of Damage or Injury. The claim is for relief in the form of money damages in the total amount of \$ 7,114.31.

SIGNED Jenny Stephen-Pierce DATE: 9-3-24  
 ADDRESS: 1822 S 17 Sheboygan, WI

MAIL TO: CLERK'S OFFICE  
828 CENTER AVE #100  
SHEBOYGAN WI 53081





# DEAN'S AUTO BODY, INC.

Deans Has the Means for All Your Collision Needs!  
1407 N 29TH ST, SHEBOYGAN, WI 53081  
Phone: (920) 457-5494  
FAX: (920) 457-6495

Workfile ID: 2044b946  
PartsShare: 879KBD

## Preliminary Estimate

### Customer: Stephen-Pierce, Jennifer

Insured: Stephen-Pierce, Jennifer      Policy #:      Claim #:  
Type of Loss:      Date of Loss:      Days to Repair: 0  
Point of Impact:

**Owner:** Stephen-Pierce, Jennifer      **Inspection Location:** DEAN'S AUTO BODY, INC.  
1822 S 17th St      1407 N 29TH ST  
Sheboygan, WI 53081      SHEBOYGAN, WI 53081  
(920) 254-2542 Cell      Repair Facility  
(920) 457-5494 Business      **Insurance Company:**

## VEHICLE

2008 CHEV Equinox LS AWD 4D UTV 6-3.4L Gasoline SFI

VIN: 2CNDL23F086347735      Interior Color:      Mileage In: 58,724      Vehicle Out:  
License:      Exterior Color:      Mileage Out:  
State:      Production Date:      Condition:      Job #:

### TRANSMISSION

Automatic Transmission  
Overdrive  
4 Wheel Drive

### POWER

Power Steering  
Power Brakes  
Power Windows  
Power Locks  
Power Mirrors

### DECOR

Dual Mirrors  
Body Side Moldings

Privacy Glass

Console/Storage

### CONVENIENCE

Air Conditioning  
Intermittent Wipers  
Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Alarm

Message Center

Rear Window Wiper

### RADIO

AM Radio

FM Radio

Stereo

Search/Seek

CD Player

Auxiliary Audio Connection

### SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Traction Control

Stability Control

Communications System

Hands Free Device

### SEATS

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

### WHEELS

Aluminum/Alloy Wheels

### PAINT

Clear Coat Paint

### OTHER

Rear Spoiler

**Preliminary Estimate**

**Customer: Stephen-Pierce, Jennifer**

2008 CHEV Equinox LS AWD 4D UTV 6-3.4L Gasoline SFI

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		<b>WINDSHIELD</b>					
open	Rpl	Windshield Chevrolet	25949078	1	470.87	Incl.	
3		<b>ROOF</b>					
4	R&I	Headliner w/o sunroof, w/o head air bag w/o GPS				Incl.	
open	Rpl	Roof panel w/o sunroof w/o digit aud	10382156	1	631.47	15.0	3.4
		Note: Note: Part no longer available					
6		Add for Clear Coat					1.4
7		<b>PILLARS, ROCKER &amp; FLOOR</b>					
8	*	Rpr LT Uniside panel				s 15.0	3.6
9		Overlap Major Adj. Panel					-0.4
10		Add for Clear Coat					0.6
11		<b>QUARTER PANEL</b>					
12	R&I	LT Quarter glass Chevrolet w/o deep tint				1.9	
13		<b>LIFT GATE</b>					
14	*	Rpr Lift gate				4.0	2.4
15		Overlap Major Adj. Panel					-0.4
16		Add for Clear Coat					0.4
open	Rpl	Spoiler	19168957	1	250.60	0.7	1.0
18		Overlap Major Non-Adj. Panel					-0.2
19	*	Add for Clear Coat					0.2
20	R&I	Molding chrome				0.2	
21	R&I	License panel				0.7	
22	Rpl	Nameplate "EQUINOX LS"	25795262	1	38.50	0.2	
23	Rpl	Nameplate "AWD"	84310387	1	38.87	0.2	
24	Rpl	Wiper arm	19120326	1	51.66	0.2	
25	Rpl	Wiper blade	19192666	1	8.25	0.1	
26		<b>REAR LAMPS</b>					
27	R&I	LT Tail lamp assy				0.3	
28		<b>REAR BUMPER</b>					
29	R&I	R&I bumper cover				0.8	
30		<b>VEHICLE DIAGNOSTICS</b>					
31	#	Pre Scan		1		1.0	M
32	#	Post Scan		1		0.5	M
33	#	OEM Diagnostic Support		1	128.00		D
34		<b>MISCELLANEOUS OPERATIONS</b>					
35	#	Rpl OEM Research And Photo Documentation		1		1.0	
36	#	Hazardous waste removal		1	8.00	T	
37	#	Refn Corrosion protection (repair area)					0.2
38	#	Rpl Cover Car		1	12.00	T	0.2

**Preliminary Estimate**

**Customer: Stephen-Pierce, Jennifer**

2008 CHEV Equinox LS AWD 4D UTV 6-3.4L Gasoline SFI

39 #

Courtesy Estimate ONLY

1

**SUBTOTALS**

**1,638.22**

**42.0**

**12.2**

**ESTIMATE TOTALS**

<b>Category</b>	<b>Basis</b>	<b>Rate</b>	<b>Cost \$</b>
Parts			1,618.22
Body Labor	40.5 hrs @	\$ 78.00 /hr	3,159.00
Paint Labor	12.2 hrs @	\$ 78.00 /hr	951.60
Mechanical Labor	1.5 hrs @	\$ 110.00 /hr	165.00
Paint Supplies	12.2 hrs @	\$ 53.00 /hr	646.60
Body Supplies	36.6 hrs @	\$ 5.00 /hr	183.00
Miscellaneous			20.00
Subtotal			6,743.42
Sales Tax	\$ 6,743.42 @	5.5000 %	370.89
<b>Grand Total</b>			<b>7,114.31</b>

**MyPriceLink Estimate ID / Quote ID:**

1257787663386157056 / 139266158



## Preliminary Estimate

---

**Customer: Stephen-Pierce, Jennifer**

2008 CHEV Equinox LS AWD 4D UTV 6-3.4L Gasoline SFI

BODY \$78/HR - REFINISH \$78/HR - MECHANICAL \$110/HR - PAINT & MATERIALS \$53/HR

As vehicle technologies increase, the costs of repairs escalate as well. With this comes a ten-fold increase in administrative duties required to process your claim. When adding even modest inflation it is inevitable at times that the hourly cost of labor must increase. Insurance "allowances" can lag behind these inevitable increases. At those times we will ask that you co-pay any differences. Most often this is not a large amount but allows us to properly train, retain, and compensate our staff for their efforts. Thus, providing you with a professional repair by a professional staff.

\*\*\*\*FOLLOW THIS LINK FOR A CO-PAY EXPLAINER VIDEO\*\*\*\*

<https://www.youtube.com/watch?v=jzfZCtmMRfo>

**\*\*NOTICE TO INSURERS:**

Dean's Auto Body, Inc. does not negotiate labor rates. Parts & Procedures are open to justification while giving consideration to OEM guidelines. PLEASE refer to the above video link for a detailed explanation of that policy.

**BLEND VS. REFINISH ADJACENT PANEL:**

With all repairs the shop will invest time and talent in tinting to negate adjacent panel "blending" However, when required, that procedure will be billed as "adjacent panel refinishing." Not a blend allowance. The basis for this change is exceptionally well validated in the attached blend study report.

As a family owned business, OUR MISSION, is to be your #1 collision repair facility. To provide you with outstanding customer care as we honestly and ethically repair your vehicle using environmentally friendly materials, the latest techniques, and up-to-date procedures. We will strive to grow our company with integrity to keep your business for life.

**\*\* All supplements must be addressed before the vehicle leaves. Any supplements left open will result in the vehicle not being delivered until the supplement is agreed upon with a copy in hand.**

Per Wisconsin Statue 628.46 - any claim not paid within 30 days is subject to a 7.5% interest charge.

**TOTAL LOSS ESTIMATES:**

Charges for a total loss estimate, with pictures and documentation to support estimate, will be charged at a minimum of 4 hours and a cost of \$90 an hour. (Costs could go up depending on what is needed to complete the written evaluation for a total loss.)

\*Disassembly to gain access to document damage will be added on accordingly at the proper shop rate.

\*Scanning and measuring for diagnosing complete damage, will be billed out for each job accordingly at the proper shop rate.

\*Any OEM repair procedures needing a subscription to gather information for the repairs will also be added per vehicle according.

STORAGE CHARGES are \$75 per day

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

## Preliminary Estimate

**Customer: Stephen-Pierce, Jennifer**

2008 CHEV Equinox LS AWD 4D UTV 6-3.4L Gasoline SFI

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DE1GV05, CCC Data Date 08/09/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.



**Preliminary Estimate**

**Customer: Stephen-Pierce, Jennifer**

2008 CHEV Equinox LS AWD 4D UTV 6-3.4L Gasoline SFI

**ALTERNATE PARTS USAGE**

2008 CHEV Equinox LS AWD 4D UTV 6-3.4L Gasoline SFI

VIN: 2CNDL23F086347735 Interior Color: Mileage In: 58,724 Vehicle Out:  
License: Exterior Color: Mileage Out:  
State: Production Date: Condition: Job #:

<b>Alternate Part Type</b>	<b>Selection Method</b>	<b># Of Times Notified Of Available Parts</b>	<b># Of Parts Selected</b>
Aftermarket	Automatically List	0	0
Optional OEM	Automatically List	0	0
Reconditioned	Automatically List	0	0
Recycled	N/A	0	0



**SHEBOYGAN CHEVROLET BUICK  
GMC CADILLAC**

3400 S BUSINESS DR, SHEBOYGAN, WI 53081  
Phone: (920) 459-6855  
FAX: (920) 459-6286

Workfile ID: 8bda3655  
PartsShare: 86NJKT  
Federal ID: 83-0747810

**Preliminary Estimate**

**Customer: STEPHEN-PIERCE, JENNIFER**

**Job Number:**

Written By: Patrick Karbe

Insured: STEPHEN-PIERCE,  
JENNIFER

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair: 0

Point of Impact: 19 All Over

**Owner:**

STEPHEN-PIERCE, JENNIFER

**Inspection Location:**

SHEBOYGAN CHEVROLET BUICK GMC  
CADILLAC

**Insurance Company:**

1822 S 17TH ST

SHEBOYGAN, WI 53081

(920) 254-2542 Cell

3400 S BUSINESS DR

SHEBOYGAN, WI 53081

Repair Facility

(920) 459-6855 Business

**VEHICLE**

2008 CHEV Equinox LS AWD 4D UTV 6-3.4L Gasoline SFI RED

VIN: 2CNDL23F086347735

Interior Color:

Mileage In: 58,724

Vehicle Out:

License: AVE6110

Exterior Color: RED

Mileage Out:

State: WI

Production Date: 6/2008

Condition:

Job #:

**TRANSMISSION**

Automatic Transmission

Overdrive

4 Wheel Drive

**POWER**

Power Steering

Power Brakes

Power Windows

Power Locks

Power Mirrors

**DECOR**

Dual Mirrors

Body Side Moldings

Privacy Glass

Console/Storage

**CONVENIENCE**

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Alarm

Message Center

Rear Window Wiper

**RADIO**

AM Radio

FM Radio

Stereo

Search/Seek

CD Player

Auxiliary Audio Connection

**SAFETY**

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Traction Control

Stability Control

Communications System

Hands Free Device

**SEATS**

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

**WHEELS**

Aluminum/Alloy Wheels

**PAINT**

Clear Coat Paint

**OTHER**

Rear Spoiler

Get live updates at [www.carwise.com/e/4SbUYF](http://www.carwise.com/e/4SbUYF)

**Preliminary Estimate**

**Customer: STEPHEN-PIERCE, JENNIFER**

**Job Number:**

2008 CHEV Equinox LS AWD 4D UTV 6-3.4L Gasoline SFI RED

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#	Rpr PreScan				0.5 M	
2	#	Rpr PostScan				0.5 M	
3	<b>WINDSHIELD</b>						
4	*	Subl Windshield Chevrolet +25%		1	432.03 X		
5	<b>ROOF</b>						
6		Repl Roof panel w/o sunroof w/o digit aud	10382156	1	631.47	15.0	3.4
		Note: NO LONGER AVAILABLE					
7		Add for Clear Coat					1.4
8		R&I Headliner w/o sunroof, w/o head air bag w/o GPS				Incl.	
9	<b>PILLARS, ROCKER &amp; FLOOR</b>						
10	#	Refn Blend upper body					1.2
11	*	Rpr LT Uniside panel				15.0	3.6
12		Overlap Major Adj. Panel					-0.4
13		Add for Clear Coat					0.6
14	<b>QUARTER PANEL</b>						
15	*	Subl LT Quarter glass Chevrolet w/o deep tint +25%		1	131.25 X		
16	<b>LIFT GATE</b>						
17	*	Rpr Lift gate				4.0	2.4
18		Overlap Major Adj. Panel					-0.4
19		Add for Clear Coat					0.4
20		Repl Spoiler	19168957	1	250.60	0.7	1.0
21		Overlap Major Non-Adj. Panel					-0.2
22	*	Add for Clear Coat					0.2
23		R&I R&I liftgate assy				Incl.	
24		R&I Molding chrome				0.2	
25		R&I License panel				0.7	
26		Repl Nameplate "EQUINOX LS"	25795262	1	38.50	0.2	
27		Repl Nameplate "AWD"	84310387	1	38.87	0.2	
28		Repl Wiper arm	19120326	1	51.66	0.2	
29		Repl Wiper blade	19192666	1	8.25	0.1	
30	<b>REAR LAMPS</b>						
31		R&I LT Tail lamp assy				0.3	
32	<b>REAR BUMPER</b>						
33		R&I R&I bumper cover				0.8	
34	<b>MISCELLANEOUS OPERATIONS</b>						
35	#	Subl Hazardous waste removal		1	3.00 T		
36	#	Repl Corrosion protection primer		1	10.00 T		
37	#	Repl Cover Car		1	5.00 T		
<b>SUBTOTALS</b>					<b>1,600.63</b>	<b>38.4</b>	<b>13.2</b>

Preliminary Estimate

Customer: STEPHEN-PIERCE, JENNIFER

Job Number:

2008 CHEV Equinox LS AWD 4D UTV 6-3.4L Gasoline SFI RED

**ESTIMATE TOTALS**

Category	Basis			Rate	Cost \$
Parts					1,582.63
Body Labor	37.4 hrs	@	\$ 70.00 /hr		2,618.00
Paint Labor	13.2 hrs	@	\$ 70.00 /hr		924.00
Mechanical Labor	1.0 hrs	@	\$ 157.99 /hr		157.99
Paint Supplies	13.2 hrs	@	\$ 50.00 /hr		660.00
Miscellaneous					18.00
Subtotal					5,960.62
Sales Tax	\$ 5,960.62	@	5.5000 %		327.83
<b>Grand Total</b>					<b>6,288.45</b>

MyPriceLink Estimate ID / Quote ID:

1255949801422331904 / 139141624

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.



## Preliminary Estimate

**Customer: STEPHEN-PIERCE, JENNIFER**

**Job Number:**

2008 CHEV Equinox LS AWD 4D UTV 6-3.4L Gasoline SFI RED

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DE1GV05, CCC Data Date 08/16/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

**Preliminary Estimate**

**Customer: STEPHEN-PIERCE, JENNIFER**

**Job Number:**

2008 CHEV Equinox LS AWD 4D UTV 6-3.4L Gasoline SFI RED

**ALTERNATE PARTS USAGE**

2008 CHEV Equinox LS AWD 4D UTV 6-3.4L Gasoline SFI RED

VIN: 2CNDL23F086347735 Interior Color: Mileage In: 58,724 Vehicle Out:  
License: AVE6110 Exterior Color: RED Mileage Out:  
State: WI Production Date: 6/2008 Condition: Job #:

<b>Alternate Part Type</b>	<b>Selection Method</b>	<b># Of Times Notified Of Available Parts</b>	<b># Of Parts Selected</b>
Aftermarket	Automatically List	0	0
Optional OEM	Manually List	0	0
Reconditioned	Manually List	0	0
Recycled	N/A	0	0



On August 16<sup>th</sup> 2024 a tree fell during a storm on my Daughters car. The car was parked in front of 1716 Elm Ave. The tree fell from 1715 Elm Ave onto the car causing major damage to the vehicle. The tree is on City Property. Alan Heusterberg, owner of the House has contacted the City numerous times about this particular tree. Also Pat Martin of 1719 Elm Ave has done the same.

Both stated they have called plenty of times regarding this particular tree due to the state of how rotten it was. In June 2024 part of this same tree fell down during a storm.

Shortly after that the tree was marked to come down. This summer several neighbors asked the crew cutting down trees on 17<sup>th</sup> Street when the tree was coming down.

They were told its not a priority. Alan was told the same information when he called, as well as Pat Martin.



on August 16<sup>th</sup> when the police officer came to take pictures she informed my husband Steve Pierce that we should contact the city. She didn't think we would be liable for this. The city workers on site that day advised us to do the same thing. We are asking for the city to review this and compensate for damages.

Thanks for your time.

Jenny Stephen-Pierce



