



MONTHLY DISTRIBUTION DEPARTMENT REPORT

March 2023

Distribution System Maintenance:

- Repaired several water main breaks within the city.
- Poured temporary service hole repair patches for water main breaks.
- Completed hydrant checks.
- Trucked out spoils.
- Hauled in fill to replenish stock.
- Distribution system valve exercising.

Building/Grounds Maintenance:

- General shop maintenance and cleaning.
- Snow removal at all Water Utility sites.
- New breakroom was completed on mezzanine of garage for C/M crew.

Equipment Maintenance:

- Performed routine maintenance and repairs on construction equipment and vehicle fleet.

Engineering:

- Bid and project manual preparation for N 20th St. and Michigan Ave/N 12th St LSL projects.
- Drawings were completed for N 20th St. and Michigan Ave/N 12th St LSL projects.
- Received WDNR approval for the Indiana Avenue water main project.
- Project and property identifications for North 15th St. and North 16th St. LSL project.
- Monthly map and database updates.



Distribution System -- March 2023

Street Valves and Hydrant Valves Installed (including water main projects and others)

Location	Date Installed	Size ("), Jt	Installed By	Type
----------	----------------	--------------	--------------	------

Total Valves Installed = 0

Street Valves and Hydrant Valves Removed

Location	Installed	Abandoned	Type
----------	-----------	-----------	------

Total Valves Removed = 0

Street Valves and Hydrant Valves Abandoned

Location	Installed	Abandoned
----------	-----------	-----------

Total Valves Abandoned = 0

Street Valves and Hydrant Valves Maintained

Location	Maintained	Size	By
----------	------------	------	----

Total Valves Maintained = 0

Hydrants Installed (including water main projects and others)

Location	Installed	Tr Size	Valve	By
----------	-----------	---------	-------	----

Total Hydrants Installed = 0

Hydrants Removed (including water main projects and others)

Location	Installed	Removed	Hyd Valve?
----------	-----------	---------	------------

Total Hydrants Removed = 0

Hydrants Abandoned (including water main projects and others)

Location	Installed	Abandoned	Tr Size	Hyd Valve?
----------	-----------	-----------	---------	------------

Total Hydrants Abandoned = 0

Hydrants Maintained/Moved (including water main projects and others)

Location	Installed	Maintained
----------	-----------	------------

Total Hydrants Maintained/Moved = 0

Water Main Breaks

Location	Date	Size
1604 N. 25th St.	3/2/2023	6"
2208 Camelot Blvd	3/27/2023	8"
1130 N. 26th St.	3/27/2023	6"

Number of Water Main Breaks= 3



SUMMARY

Number of feet of 4 inch water main installed	0.0	water main
Number of feet of 6 inch hydrant lead installed	0.0	
Number of feet of 6 inch water main installed	0.0	
Number of feet of 8 inch water main installed	0.0	
Number of feet of 12 inch water main installed	0.0	
Number of feet of 16 inch water main installed	0.0	
Number of feet of 20 inch water main installed	0.0	
Number of feet of 24 inch water main installed	0.0	
Number of feet of water main abandoned or removed	0.0	
Number of water main breaks repaired	3	
Number of hydrants installed	0	hydrants
Number of hydrants removed or abandoned	0	
Number of hydrants maintained or moved	0	
Number of street valves installed	0	valves
Number of hydrant valves installed	0	
Number of street valves removed or abandoned	0	
Number of hydrant valves removed or abandoned	0	
Number of valves maintained	65	
Number of water connections installed	0	