

**CITY OF SHEBOYGAN
R. O. 100-23-24**

BY CITY CLERK.

FEBRUARY 5, 2024.

Submitting a claim from Alex Xiong for alleged damages to vehicle caused by a snow plow.

DATE RECEIVED 1-29-2024

RECEIVED BY MKC

CLAIM NO. 20-23

CITY OF SHEBOYGAN NOTICE OF DAMAGE OR INJURY

INSTRUCTIONS: TYPE OR PRINT IN BLACK INK

JAN 29 2024

- 1. Notice of death, injury to persons or to property must be filed not later than 120 days after the occurrence.
- 2. Attach and sign additional supportive sheets, if necessary.
- 3. This notice form must be signed and filed with the Office of the City Clerk.

4. TWO ESTIMATES MUST BE ATTACHED IF YOU ARE CLAIMING DAMAGE TO A VEHICLE.

- 1. Name of Claimant: Alex Xiong
- 2. Home address of Claimant: 1614 Heller Avenue, Sheboygan, WI 53081
- 3. Home phone number: 215-820-8978
- 4. Business address and phone number of Claimant: _____
- 5. When did damage or injury occur? (date, time of day) 1/12/24 9:10 p.m.
- 6. Where did damage or injury occur? (give full description) Left back of car at 1614 Heller Avenue. Given a Crashdocs.org card, the report number is C24-00671
- 7. How did damage or injury occur? (give full description) City Snow plow hit the back of car parked at 1614 Heller Avenue.
- 8. If the basis of liability is alleged to be an act or omission of a City officer or employee, complete the following:
 - (a) Name of such officer or employee, if known: N/A
 - (b) Claimant's statement of the basis of such liability: N/A
- 9. If the basis of liability is alleged to be a dangerous condition of public property, complete the following:
 - (a) Public property alleged to be dangerous: N/A
 - (b) Claimant's statement of basis for such liability: N/A

10. Give a description of the injury, property damage or loss, so far as is known at this time. (If there were no injuries, state "NO INJURIES").

N/A

11. Name and address of any other person injured:

N/A

12. Damage estimate: (You are not bound by the amounts provided here.)

Auto:

\$ 5420.25

Property:

\$ N/A

Personal injury:

\$ N/A

Other: (Specify below

\$ N/A

TOTAL

\$ 5420.25


Damaged vehicle (if applicable)

Make: Toyota Model: Corolla Year: 2010 Mileage: 175,170

Names and addresses of witnesses, doctors and hospitals: _____

FOR ALL ACCIDENT NOTICES, COMPLETE THE FOLLOWING DIAGRAM IN DETAIL. BE SURE TO INCLUDE NAMES OF ALL STREETS, HOUSE NUMBERS, LOCATION OF VEHICLES, INDICATING WHICH IS CITY VEHICLE (IF APPLICABLE), WHICH IS CLAIMANT VEHICLE, LOCATION OF INDIVIDUALS, ETC.

NOTE: If diagrams below do not fit the situation, attach proper diagram and sign.



SIGNATURE OF CLAIMANT

[Signature]

DATE

1/29/24

DATE RECEIVED _____

RECEIVED BY _____

CLAIM NO. _____

CLAIM

Claimant's Name: Alex Xiong

Auto \$ 5420.25

Claimant's Address: 1614 Heller Avenue

Property \$ N/A

Personal Injury \$ N/A

Claimant's Phone No. 215-820-8978

Other (Specify below) \$ N/A

TOTAL \$ 5420.25

PLEASE INCLUDE COPIES OF ALL BILLS, INVOICES, ESTIMATES, ETC.

WARNING: IT IS A CRIMINAL OFFENSE TO FILE A FALSE CLAIM.
(WISCONSIN STATUTES 943.395)

The undersigned hereby makes a claim against the City of Sheboygan arising out of the circumstances described in the Notice of Damage or Injury. The claim is for relief in the form of money damages in the total amount of \$ 5420.25.

SIGNED [Signature]

DATE: 1/29/24

ADDRESS: 1614 Heller Avenue

MAIL TO: CLERK'S OFFICE
828 CENTER AVE #100
SHEBOYGAN WI 53081

**SHEBOYGAN CHEVROLET BUICK
GMC CADILLAC**

3400 S BUSINESS DR, SHEBOYGAN, WI 53081
Phone: (920) 459-6855
FAX: (920) 459-6286

Workfile ID: 57d25601
PartsShare: 7LqX9Y
Federal ID: 83-0747810

Preliminary Estimate

Customer: XIONG, ALEX

Job Number:

Written By: Jeff Wiegand

Insured: XIONG, ALEX
Type of Loss:
Point of Impact: 08 Left Qtr Post (Left Side)

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
XIONG, ALEX

1614 HELLER AVE.
SHEBOYGAN, WI 53081
(215) 820-8978 Cell

Inspection Location:
SHEBOYGAN CHEVROLET BUICK GMC
CADILLAC
3400 S BUSINESS DR
SHEBOYGAN, WI 53081
Repair Facility
(920) 459-6855 Business

Insurance Company:

VEHICLE

2010 TOYO Corolla S Automatic 4D SED 4-1.8L Gasoline SFI SILVER

VIN: 2T1BU4EE6AC251587	Interior Color:	Mileage In: 175,172	Vehicle Out:
License: ABM2719	Exterior Color: SILVER	Mileage Out:	
State: WI	Production Date: 8/2009	Condition:	Job #:

TRANSMISSION

Automatic Transmission
Overdrive

POWER

Power Steering
Power Brakes
Power Locks
Power Mirrors

DECOR

Dual Mirrors
Console/Storage

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel

RADIO

AM Radio
FM Radio
Stereo

Search/Seek
CD Player
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
Front Side Impact Air Bags
Head/Curtain Air Bags

SEATS

Cloth Seats
Bucket Seats

WHEELS

Wheel Covers

PAINT

Clear Coat Paint

OTHER

Fog Lamps
Traction Control
Stability Control
Rear Spoiler
California Emissions
Power Trunk/Liftgate

Get live updates at www.carwise.com/e/4GFP7p

Preliminary Estimate

Customer: XIONG, ALEX

Job Number:

2010 TOYO Corolla S Automatic 4D SED 4-1.8L Gasoline SFI SILVER

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		PILLARS, ROCKER & FLOOR					
2	R&I	LT Rocker molding S, XRS				0.9	
3		REAR DOOR					
4	*	Blnd LT Outer panel (HSS)					<u>1.0</u>
5	R&I	LT Belt molding				0.3	
6	R&I	LT Handle, outside US built silver				0.4	
7	R&I	LT R&I trim panel				0.4	
8		BACK GLASS					
9	*	Subl Back glass Toyota US built +25%		1	<u>168.75</u> X		
open		Repl Molding US built	NOT USED	1			
11		Repl Dam	6481312180	1	11.64		
12		QUARTER PANEL					
13		Repl LT Stone guard w/cold area spec	5874202130	1	19.65	0.2	
14		Repl LT Quarter panel	6160202170	1	945.23	16.5	3.2
15		Add for Clear Coat					1.3
16	#	Refn Blend upper body					1.2
17	*	Blnd Fuel door					<u>0.2</u>
18		REAR LAMPS					
19	*	Repl LKQ LT Combo lamp assy +25%	8156112A50	1	81.25	<u>0.3</u>	
20		REAR BUMPER					
21	R&I	R&I bumper cover				Incl.	
22		MISCELLANEOUS OPERATIONS					
23	#	Subl Hazardous waste removal		1	3.00 T		
24	#	Repl Seam sealer/caulking		1	12.00 T	0.5	
25	#	Repl Cover Car		1	5.00 T		
26	#	R&I LR DOOR BODYSIDE MLDG.				0.5	
SUBTOTALS					1,246.52	20.0	6.9

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			1,226.52
Body Labor	20.0 hrs @	\$ 67.00 /hr	1,340.00
Paint Labor	6.9 hrs @	\$ 67.00 /hr	462.30
Paint Supplies	6.9 hrs @	\$ 47.00 /hr	324.30
Miscellaneous			20.00
Subtotal			3,373.12
Sales Tax	\$ 3,373.12 @	5.5000 %	185.52
Grand Total			3,558.64

Preliminary Estimate

Customer: XIONG, ALEX

Job Number:

2010 TOYO Corolla S Automatic 4D SED 4-1.8L Gasoline SFI SILVER

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ARM8428, CCC Data Date 01/17/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2023 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

Preliminary Estimate

Customer: XIONG, ALEX

Job Number:

2010 TOYO Corolla S Automatic 4D SED 4-1.8L Gasoline SFI SILVER

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: XIONG, ALEX

Job Number:

2010 TOYO Corolla S Automatic 4D SED 4-1.8L Gasoline SFI SILVER

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
19	LKQ Corp 2101 Beloit Avenue Janesville WI 53546 (800) 362-9451	#~355064385 LKQ LT Combo lamp assy +25% Tail Lamp QTR MTD, LH, NORTH AMERICA BUILT,S#\$V3332 Quote: 2352110706 Expires: 03/04/24	\$ 65.00

Preliminary Estimate

Customer: XIONG, ALEX

Job Number:

2010 TOYO Corolla S Automatic 4D SED 4-1.8L Gasoline SFI SILVER

ALTERNATE PARTS USAGE

2010 TOYO Corolla S Automatic 4D SED 4-1.8L Gasoline SFI SILVER

VIN: 2T1BU4EE6AC251587 Interior Color: Mileage In: 175,172 Vehicle Out:
License: ABM2719 Exterior Color: SILVER Mileage Out:
State: WI Production Date: 8/2009 Condition: Job #:

Alternate Part Type	Selection Method	# Of Times Notified Of Available Parts	# Of Parts Selected
Aftermarket	Automatically List	0	0
Optional OEM	Manually List	0	0
Reconditioned	Manually List	0	0
Recycled	N/A	1	1



DEAN'S AUTO BODY, INC.

Deans Has the Means for All Your Collision Needs!
1407 N 29TH ST, SHEBOYGAN, WI 53081
Phone: (920) 457-5494
FAX: (920) 457-6495

Workfile ID: 8deb01e3
PartsShare: 7LT6Lb

Preliminary Estimate

Customer: Xiong, Alex

Written By: Joe Black

Insured: Xiong, Alex Policy #: Claim #:
Type of Loss: Date of Loss: Days to Repair: 0
Point of Impact: 08 Left Qtr Post (Left Side)

Owner: Xiong, Alex **Inspection Location:** DEAN'S AUTO BODY, INC.
1614 Heller Ave 1407 N 29TH ST
Sheboygan, WI 53081 SHEBOYGAN, WI 53081
(215) 820-8978 Cell Repair Facility
(920) 457-5494 Business **Insurance Company:**

VEHICLE

2010 TOYO Corolla S Automatic 4D SED 4-1.8L Gasoline SFI Classic Silver

VIN: 2T1BU4EE6AC251587 Interior Color: Mileage In: 175,296 Vehicle Out:
License: ABM-2719 Exterior Color: Classic Silver Mileage Out:
State: WI Production Date: 8/2009 Condition: Fair Job #:

TRANSMISSION

Automatic Transmission
Overdrive

POWER

Power Steering
Power Brakes
Power Locks
Power Mirrors

DECOR

Dual Mirrors
Console/Storage

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel

RADIO

AM Radio
FM Radio
Stereo

Search/Seek
CD Player
Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
Front Side Impact Air Bags
Head/Curtain Air Bags

SEATS

Cloth Seats
Bucket Seats

WHEELS

Wheel Covers

PAINT

Clear Coat Paint

OTHER

Fog Lamps
Traction Control
Stability Control
Rear Spoiler
California Emissions
Power Trunk/Liftgate

Preliminary Estimate

Customer: Xiong, Alex

2010 TOYO Corolla S Automatic 4D SED 4-1.8L Gasoline SFI Classic Silver

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		RESTRAINT SYSTEMS					
2	*	R&I LT Head air bag US built				m 0.7	M
3		ROOF					
4		R&I R&I headliner				3.1	
5		PILLARS, ROCKER & FLOOR					
6		R&I LT Rocker molding S, XRS				0.9	
7		REAR DOOR					
8		R&I LT R&I door assy w/power units				1.1	
9		Refn LT Door shell w/power window US built (HSS)					1.9
10		Add for Clear Coat					0.8
11		R&I LT Belt molding				0.3	
12	#	R&I LT Body Side molding				0.3	
13		R&I LT Handle, outside US built silver				0.4	
14		R&I LT R&I trim panel				0.4	
15	#	Clean & re-tape mldg(s)		1		0.5	
16	#	Rpr Color sand and buff					
Note: (If needed / open until time of repair) CCC Guide to Estimating G39 . Refinished panels may or may not require a varying amount of wet sanding, compound rub-out or buffing operations in order to match original . Each panel requiring wet sand, rub-out and/or buff (refinish or blend) Add 30% of full base refinish time Math 1.9 x 30% = .6 LT Rear door panel only							
17		BACK GLASS					
18		R&I Back glass Toyota US built					Incl.
19		QUARTER PANEL					
20		Repl LT Quarter panel	6160202170	1	945.23	16.5	3.2
21		Overlap Major Adj. Panel					-0.4
22		Add for Clear Coat					0.6
23		Refn Fuel door					0.3
24		Add for Clear Coat					0.1
25		Repl LT End panel	6169802910	1	73.55	3.4	0.4
26		Overlap Minor Panel					-0.2
27		Add for Clear Coat					0.1
28		Repl LT Stone guard w/cold area spec	5874202130	1	19.65	0.2	
29	#	Refn Feather edge prime and block					0.5
Note: CCC Guide to Estimating G34 PRIME & BLOCK . Prime & block (high build/primer-filler) is a required procedure							

Preliminary Estimate

Customer: Xiong, Alex

2010 TOYO Corolla S Automatic 4D SED 4-1.8L Gasoline SFI Classic Silver

that restores a repaired panel surface, including the joined areas of replaced welded panels, from 150-grit finish to NEW UNDAMAGED condition.

30 # Rpr Color sand and buff
 Note: (If needed / open until time of repair)
 CCC Guide to Estimating G39

. Refinished panels may or may not require a varying amount of wet sanding, compound rub-out or buffing operations in order to match original

. Each panel requiring wet sand, rub-out and/or buff (refinish or blend)

Add 30% of full base refinish time

Math 3.2 x 30% = 1.0

LT Quarter panel only

31 TRUNK LID

32 R&I R&I trunk lid 0.5

33 REAR LAMPS

34 ** Repl A/M CAPA LT Combo lamp assy 8156002460 1 120.00 Incl.

35 REAR BUMPER

36 R&I R&I bumper cover Incl.

37 VEHICLE DIAGNOSTICS

38 # OEM Diagnostic Support 1 128.00 D

39 # Pre Scan 1 1.0 M

40 # Post Scan 1 0.5 M

Note: Manufacture Requires Scan

41 MISCELLANEOUS OPERATIONS

42 # Repl OEM Research And Photo Documentation 1 1.0

43 # Hazardous waste removal 1 8.00 T

44 # Repl Cover Car 1 12.00 T 0.2

45 # Refn Corrosion protection (repair area) 0.2

46 # Repl Flex additive 1 12.00 T

47 # R&I Rear Interior and Seats 2.5

48 # Disconnect battery cable 1 0.2

49 # Repl Urethane kit 1 31.25

50 # ***Possible hidden damage*** 1

SUBTOTALS 1,349.68 33.7 7.5

Preliminary Estimate

Customer: Xiong, Alex

2010 TOYO Corolla S Automatic 4D SED 4-1.8L Gasoline SFI Classic Silver

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			1,317.68
Body Labor	31.5 hrs @	\$ 78.00 /hr	2,457.00
Paint Labor	7.5 hrs @	\$ 78.00 /hr	585.00
Mechanical Labor	2.2 hrs @	\$ 110.00 /hr	242.00
Paint Supplies	7.5 hrs @	\$ 53.00 /hr	397.50
Body Supplies	21.3 hrs @	\$ 5.00 /hr	106.50
Miscellaneous			32.00
Subtotal			5,137.68
Sales Tax	\$ 5,137.68 @	5.5000 %	282.57
Grand Total			5,420.25
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			5,420.25

Preliminary Estimate

Customer: Xiong, Alex

2010 TOYO Corolla S Automatic 4D SED 4-1.8L Gasoline SFI Classic Silver

BODY \$78/HR - REFINISH \$78/HR - MECHANICAL \$110/HR - PAINT & MATERIALS \$53/HR

As vehicle technologies increase, the costs of repairs escalate as well. With this comes a ten-fold increase in administrative duties required to process your claim. When adding even modest inflation it is inevitable at times that the hourly cost of labor must increase. Insurance "allowances" can lag behind these inevitable increases. At those times we will ask that you co-pay any differences. Most often this is not a large amount but allows us to properly train, retain, and compensate our staff for their efforts. Thus, providing you with a professional repair by a professional staff.

****FOLLOW THIS LINK FOR A CO-PAY EXPLAINER VIDEO****

<https://www.youtube.com/watch?v=jzfZCtmMRfo>

**NOTICE TO INSURERS:

Dean's Auto Body, Inc. does not negotiate labor rates. Parts & Procedures are open to justification while giving consideration to OEM guidelines. PLEASE refer to the above video link for a detailed explanation of that policy.

BLEND VS. REFINISH ADJACENT PANEL:

With all repairs the shop will invest time and talent in tinting to negate adjacent panel "blending" However, when required, that procedure will be billed as "adjacent panel refinishing." Not a blend allowance. The basis for this change is exceptionally well validated in the attached blend study report.

As a family owned business, OUR MISSION, is to be your #1 collision repair facility. To provide you with outstanding customer care as we honestly and ethically repair your vehicle using environmentally friendly materials, the latest techniques, and up-to-date procedures. We will strive to grow our company with integrity to keep your business for life.

** All supplements must be addressed before the vehicle leaves. Any supplements left open will result in the vehicle not being delivered until the supplement is agreed upon with a copy in hand.

Per Wisconsin Statue 628.46 - any claim not paid within 30 days is subject to a 7.5% interest charge.

TOTAL LOSS ESTIMATES:

Charges for a total loss estimate, with pictures and documentation to support estimate, will be charged at a minimum of 4 hours and a cost of \$90 an hour. (Costs could go up depending on what is needed to complete the written evaluation for a total loss.)

*Disassembly to gain access to document damage will be added on accordingly at the proper shop rate.

*Scanning and measuring for diagnosing complete damage, will be billed out for each job accordingly at the proper shop rate.

*Any OEM repair procedures needing a subscription to gather information for the repairs will also be added per vehicle according.

STORAGE CHARGES are \$75 per day

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

Preliminary Estimate

Customer: Xiong, Alex

2010 TOYO Corolla S Automatic 4D SED 4-1.8L Gasoline SFI Classic Silver

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ARM8428, CCC Data Date 01/09/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2023 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

Preliminary Estimate

Customer: Xiong, Alex

2010 TOYO Corolla S Automatic 4D SED 4-1.8L Gasoline SFI Classic Silver

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: Xiong, Alex

2010 TOYO Corolla S Automatic 4D SED 4-1.8L Gasoline SFI Classic Silver

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
28	Wilde Toyota 3225 S 108th St West Allis WI 53227	#5874202130 LT Stone guard w/cold area spec Quote: 1752073722 Expires: 02/24/24	\$ 19.65
34	Keystone, Inc 5050 N WREN DRIVE APPLETON WI 54913 (920) 731-3030	#TO2800175C A/M CAPA LT Combo lamp assy Quote: 2360730237 Expires: 03/11/24	\$ 120.00

Preliminary Estimate

Customer: Xiong, Alex

2010 TOYO Corolla S Automatic 4D SED 4-1.8L Gasoline SFI Classic Silver

ALTERNATE PARTS USAGE

2010 TOYO Corolla S Automatic 4D SED 4-1.8L Gasoline SFI Classic Silver

VIN: 2T1BU4EE6AC251587 Interior Color: Mileage In: 175,296 Vehicle Out:
License: ABM-2719 Exterior Color: Classic Silver Mileage Out:
State: WI Production Date: 8/2009 Condition: Fair Job #:

Alternate Part Type	Selection Method	# Of Times Notified Of Available Parts	# Of Parts Selected
Aftermarket	Automatically List	1	1
Optional OEM	Automatically List	0	0
Reconditioned	Automatically List	0	0
Recycled	N/A	0	0