

# MONTHLY DISTRIBUTION DEPARTMENT REPORT January 2024

### **Distribution System Maintenance:**

- Repaired main breaks throughout the city.
- Temporary patches poured for water main break service holes.
- Worked on repairing street barricades.
- Trucked out spoils.
- Hauled in fill to replenish stock.

#### Taps:

- 2" tap at 1244 Heerman Ct.
- 1" tap at 903 High Avenue . LSL was removed from system.

#### **Building/Grounds Maintenance:**

- General shop maintenance and cleaning.
- Aided Operations in prep work on filters 3 and 4.
- Started remodel of office and meter shop offices.

## **Equipment Maintenance:**

• Performed routine maintenance and repairs on construction equipment and vehicle fleet.

#### **Engineering:**

- Obtained WDNR approval for Lincoln Avenue watermain project.
- Finished Lincoln Ave and Swift Ave LSL project design and posted to bid.
- Monthly map and database updates.
- Started as-builts for 2023 watermain projects.

#### Training:

• C/M and Engineering staff attended virtual training for WDNR certification preparation.



# **Distribution System -- January 2024**

Street Valves and Hydrant Valves Installed (including water main projects and others)

Location	Date Installed	Size ("), Jt	Installed By	Type
Location	Date Histalicu	SIZE ( ), Jt	instancu Dy	1 1 1 1

Total Valves Installed = 0

Street Valves and Hydrant Valves Removed

Location	Installed	Abandoned	Type

Total Valves Removed = 0

Street Valves and Hydrant Valves Abandoned

T /*	T , 11 1	41 1 1
Location	Installed	Abandoned

Total Valves Abandoned = 0

Street Valves and Hydrant Valves Maintained

Total Valves Maintained = 0

Hydrants Installed (including water main projects and others)

Location   Installed   Tr Size   Valve   By
---

Total Hydrants Installed = 0

Hydrants Removed (including water main projects and others)

Location	Installed	Removed	Hyd Valve?
----------	-----------	---------	------------

Total Hydrants Removed = 0

Hydrants Abandoned (including water main projects and others)

_	,	 U	1 3					
	Location			Installed	Abandoned	Tr Size	Hvd Valve?	

Total Hydrants Abandoned = 0

Hydrants Maintained/Moved (including water main projects and others)

	 	1 2		
Location			Installed	Maintained

Total Hydrants Maintained/Moved = 0

#### Water Main Breaks

Location	Date	Size
2420 N. 7th St.	1/18/2024	6"
1602 Huron Ave	1/19/2024	4"
2026 New Jersey Ave	1/19/2024	12"
2521 Saemann Ave	1/23/2024	6"

Number of Water Main Breaks= 4



# SUMMARY

SCHIMINI		
Number of feet of 4 inch water main installed	0.0	water main
Number of feet of 6 inch hydrant lead installed	0.0	
Number of feet of 6 inch water main installed	0.0	
Number of feet of 8 inch water main installed	0.0	
Number of feet of 12 inch water main installed	0.0	
Number of feet of 16 inch water main installed	0.0	
Number of feet of 20 inch water main installed	0.0	
Number of feet of 24 inch water main installed	0.0	
Number of feet of water main abandoned or removed	0.0	
Number of water main breaks repaired	4	
Number of hydrants installed	0	hydrants
Number of hydrants removed or abandoned	0	
Number of hydrants maintained or moved	0	
Number of street valves installed	0	valves
Number of hydrant valves installed	0	
Number of street valves removed or abandoned	0	
Number of hydrant valves removed or abandoned	0	
Number of valves maintained	0	
Number of water connections installed	2	



