R. O. No. <u>88 - 22 - 23</u>. By CITY CLERK. December 5, 2022.

Submitting a claim from Cristy Murray for alleged damages to her vehicle when it was hit by a garbage truck.

FAP

CITY CLERK

11-28-0 DATE RECEIVED

RECEIVED BY

CLAIM NO.

NOV 2 8 2022

CITY OF SHEBOYGAN NOTICE OF DAMAGE OR INJURY

INSTRUCTIONS: TYPE OR PRINT IN BLACK INK

- Notice of death, injury to persons or to property must be filed not later than <u>120 days</u> after the occurrence.
- Attach and sign additional supportive sheets, if necessary.
- 3. This notice form must be signed and filed with the Office of the City Clerk.

4. TWO ESTIMATES MUST BE ATTACHED IF YOU ARE CLAIMING DAMAGE TO A VEHICLE.

Cristy Murro Name of Claimant: 1. Home address of Claimant: 1521 Kaufmann Ave Sheboygan 2. Home phone number: (920) 362-3664 З. 4. Business address and phone number of Claimant: When did damage or injury occur? (date, time of day) 9/2/22 11,00 AM 5. Where did damage or injury occur? (give full description) dowl (5 6. ee attached rear bumper (e Report How did damage or injury occur? (give full description) (galbage fouck 7. nt go back up and hit car as Jas see attached police report If the basis of liability is alleged to be an act or omission of a City officer or 8. employee, complete the following: (a) Name of such officer or employee, if known: (b) Claimant's statement of the basis of such liability: If the basis of liability is alleged to be a dangerous condition of public property, 9. complete the following: (a) Public property alleged to be dangerous: (b) Claimant's statement of basis for such liability:

<		
time. (If there were	of the injury, property damage or loss, so far as is known no injuries, state "NO INJURIES"). MICS damage to clar bumper	
	and authorize to rear kumper	
11. Name and address of	any other person injured:	
12. Damage estimate: (1	ou are not bound by the amounts provided here.)	
Auto:	\$ 10100.93	
Property:	\$	
Personal injury:	\$	
Other: (Specify belo	w \$	
	TOTAL \$1060.93	
-		
Damaged vehicle (if		
Make: Ford	Model: FOCUS Year: 2005 Mileage: 162,9	ole
Names and addresses	of witnesses, doctors and hospitals:	
NAMES OF ALL STREETS, H	S, COMPLETE THE FOLLOWING DIAGRAM IN DETAIL. BE SURE TO DUSE NUMBERS, LOCATION OF VEHICLES, INDICATING WHICH IS CITY S CLAIMANT VEHICLE, LOCATION OF INDIVIDUALS, ETC.	INCLUDE VEHICLE
NOTE: If diagrams below	do not fit the situation, attach proper diagram and sign.	
$7 \wedge$	K / K / K / K / K / K / K / K / K / K /	e
	FOR OTHER ACCIDENTS	port
/		POLI
CURB		
SIGNATURE OF CLAIMAN	T Chisty Murray DATE 10/28/2	2

F

~ ;				
DATE RECEIVED			RECEIVED BY	
			CLAIM NO.	
	CL	LAIM		
Claimant's Name:	Cristy Murra	4	Auto	\$ 1060.93
Claimant's Address:	1521 Kaufmann	Due	Property	\$
	Sheboygan 5308	<1	Personal Injury	\$
Claimant's Phone No.	(920)362-3664		Other (Specify below)	\$
			TOTAL	\$1060.93

PLEASE INCLUDE COPIES OF ALL BILLS, INVOICES, ESTIMATES, ETC.

WARNING: IT IS A CRIMINAL OFFENSE TO FILE A FALSE CLAIM. (WISCONSIN STATUTES 943.395)

The undersigned hereby makes a claim against the City of Sheboygan arising out of the circumstances described in the Notice of Damage or Injury. The claim is for relief in the form of money damages in the total amount of $\frac{5}{0.03}$.

SIGNED Custy Murray	DATE: 10/28/22
ADDRESS: 1521 Kaufmann	Ave Sheboygan wi 53081

MAIL TO: CLERK'S OFFICE 828 CENTER AVE #100 SHEBOYGAN WI 53081

\$ 1 SHEBOYGAN POLICE DEPARTMENT G7L0FQBC6T WISCONSIN MOTOR VEHICLE 1315 N 23RD ST CRASH REPORT SHEBOYGAN, WI 53081 C22-16329 (920) 459-3333 Primary Crash Document# Agency Crash Number Investigating Officer/Deputy Document Number Override OFFICER J. BECKER Date Arrived Time Arrived Crash Date Crash Time G7L0FQBC61 09/02/2022 11:12 AM 09/02/2022 11:00 AM Time Notified Date Notified Total Units Total Injured Total Killed 00 11:05 AM 00 09/02/2022 02 Reporting Work Zone Trailer or Towed On Emergency Hit and Run Lane Closure Threshold School Bus Related Tags Government Active School Zone NO Property Crash Type Secondary Amended Reportable DT4000 (STANDARD CRASH) Crash Description Diagram Reconstruction By Photos By BECKER 485 Additional Information PHOTOS 01 -0 02

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS ON 1500 BLOCK OF KAUFMANN AVE PICKING UP GARBAGE CANS WITH THE GARBAGE TRUCK, TRAVELING EASTBOUND DOWN THE ROAD. UNIT 1 SET DOWN A GARBAGE CAN IN FRONT OF 1521 KAUFMANN AVE, BUT THE ARM WAS STILL OUT WHEN UNIT 1 BEGAN TO DRIVE TO THE NEXT GARBAGE BIN THIS CAUSED THE ARM OF THE GARBAGE TRUCK THE COLLIDE. WITH THE REAR OF UNIT 2 THAT WAS PARKED ON THE SOUTH SIDE OF THE ROAD. PARTS OF THE ARM ON UNIT 2 BROKE OFF AND THE REAR BUMPER OF UNIT 1 HAD A LARGE DENT AND PAINT SCRAPE. PICTURES TAKEN AND ATTACHED TO THE CASE. CRASH DOCUMENT CARD PROVIDED TO BOTH UNIT 1 AND 2.

Crash Date 09/02/2022 Crash Time 11:00 AM

G7L0FQBC6T

C22-16329

× .

έ.

WISCONSIN MOTOR VEHICLE CRASH REPORT

SHEBOYGAN POLICE DEPARTMENT 1315 N 23RD ST SHEBOYGAN, WI 53081 (920) 459-3333

	Loc	ation			A REPORT OF TAXABLE				and the second second second	
2		1513 KAUFMANN AVE				Latitude			Longitue	de
		FTE				43.714170423			-87.725	5926203
		S 16TH ST				X Coordin	ate		Y Coord	linate
	(HO	USE/BUILDING 1513)				441520.7	75		484038	
	IN T	THE CITY OF SHEBOY	GAN			Structure Type				
	10000	SHEBOYGAN COUNTY				HOUSE/BUILDING				
						1				
		sh Scene								
	First	tHarmful Event				FirstHarm	fulEventL	ocation		
	MO	TOR VEH IN TRANSPO	ORT			ON ROA	DWAY			
	Man	ner of Collision				Light Con	dition			
	07 -	07 - SIDESWIPE/SAME DIRECTION					нт			
	Roa	d Surface Condition(s)				Roadway	Factor(s)			
	DR									
	UR	r								
	Env	ironment Factor(s)				1				
	NO	NF				NONE				
	Wea	ather Condition(s)								
	CLO	OUDY								
	A -:	nal Turna								
	Anin	nalType					o Trafficwa			
							CWAY - O			
		sh Classification - Location						Jurisdiction		
		BLIC PROPERTY				NO SPEC	CIAL JUR	ISDICTION		
	Trib	alLand				Access Control				Special Study
						FULL CONTROL				
	With	in Interchange Area	Junction Location		Intersectio	on Type				
	NO		NON-JUNCTION		NOT AN	INTERSE	CTION			
	Ini	+ Cummany	and the second reaction of the second second							and the second se
					COST AND		Station in the	A COLORADO TO A COLORADO	CHARLES AND	Statute and an experimental states of the second
		t Summary		Vehicle Op	erating As C	lassification		UnitType		
	Unit	Status		Vehicle Op	erating As C	lassification		Unit Type		
	Unit	Status TRANSIT		Vehicle Op A CLASS	erating As C	lassification		TRUCK	- Endomo	
	Unit IN T Veh	Status TRANSIT icle Type			erating As C	lassification		1	s Endorse	ments
	Unit IN T Veh	Status TRANSIT icle Type RAIGHT TRUCK (INSE		A CLASS				TRUCK Operating A		
	Unit IN T Veh STF Tota	Status TRANSIT icle Type	RT TRUCK)	A CLASS			TotalTrai	TRUCK Operating A	TotalHaz	ments Mat Types
	Unit IN T Vehi STF Tota 1	Status IRANSIT icle Type RAIGHT TRUCK (INSEI Il Occs	Train/Bus#Recorded	A CLASS	tions Issued	l	Total Trai 0	TRUCK Operating A lers	Total Haz 0	MatTypes
01	Unit IN T Veh STF Tota 1 Insu	Status IRANSIT icle Type RAIGHT TRUCK (INSEI Il Occs rance?	Train/Bus # Recorded Direction Of Travel	A CLASS	tions Issued CrashTire	l	Total Trai 0 Speed Lir	TRUCK Operating A lers	Total Haz 0 Total Lan	MatTypes
01	Unit IN T Vehi STF Tota 1 Insu YES	Status IRANSIT icle Type RAIGHT TRUCK (INSEI Il Occs rance?	Train/Bus # Recorded Direction Of Travel EASTBOUND	A CLASS	tions Issued Crash Tire Mark	l	Total Trai 0	TRUCK Operating A lers	Total Haz 0 Total Lan 2	Mat Types es
01	Unit IN T Veh STF Tota 1 Insu YES Mos	Status (RANSIT icle Type RAIGHT TRUCK (INSEI I Occs rance? S tHarmful Event: Collision \	Train/Bus # Recorded Direction Of Travel EASTBOUND With	A CLASS	tions Issued Crash Tire Mark Inction	1	Total Trai 0 Speed Lir	TRUCK Operating A lers mit Emergency	Total Haz 0 Total Lan 2 Motor Veh	Mat Types es
01	Unit IN T Veh STF Tota 1 Insu YES Mos PAF	Status (RANSIT icle Type RAIGHT TRUCK (INSEL I Occs rance? S tHarmful Event: Collision \ RKED MOTOR VEHICL	Train/Bus # Recorded Direction Of Travel EASTBOUND With	A CLASS	tions Issued Crash Tire Mark Inction IAL FUNC	1	Total Trai 0 Speed Lir	TRUCK Operating A lers mit Emergency NOT APPI	Total Haz 0 Total Lan 2 Motor Veh .ICABLE	Mat Types es icle Use
01	Unit IN T Vehi STF Tota 1 Insu YES Mos PAF Trafi	Status (RANSIT icle Type RAIGHT TRUCK (INSEI I Occs rance? S tHarmful Event: Collision \ RKED MOTOR VEHICL fic Way	Train/Bus # Recorded Direction Of Travel EASTBOUND With	A CLASS	CrashTire Mark Inction IAL FUNC	1	Total Trai 0 Speed Lir	TRUCK Operating A lers mit Emergency NOT APPI Traffic Cont	Total Haz 0 Total Lan 2 Motor Veh .ICABLE	Mat Types es icle Use
01	Unit IN T Vehi STF Tota 1 Insu YES Mos PAF Trafi TWO	Status (RANSIT icle Type RAIGHT TRUCK (INSEI Il Occs rance? S tHarmful Event: Collision N RKED MOTOR VEHICL fic Way D-WAY, NOT DIVIDED	Train/Bus # Recorded Direction Of Travel EASTBOUND With	A CLASS	tions Issued Crash Tire Mark Inction IAL FUNC trol ROL	1	Total Trai 0 Speed Lir	TRUCK Operating A lers mit Emergency NOT APPI Traffic Cont NO	Total Haz 0 Total Lan 2 Motor Veh ICABLE	Mat Types es icle Use
01	Unit IN T Veh STF Tota 1 Insu YES Mos PAF Traft TWO Surf	Status (RANSIT icle Type RAIGHT TRUCK (INSEI Il Occs rance? S tHarmful Event: Collision N RKED MOTOR VEHICL fic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded Direction Of Travel EASTBOUND With E	A CLASS	tions Issued Crash Tire Mark Inction IAL FUNC trol ROL ature	1	Total Trai 0 Speed Lir	TRUCK Operating A lers mit Emergency NOT APPI Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh ICABLE	Mat Types es icle Use
10	Unit IN T Veh STF Tota 1 Insu YES PAF Traff Two Surf BLA	Status (RANSIT icle Type RAIGHT TRUCK (INSEI Il Occs rance? S Harmful Event: Collision N RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS	Train/Bus # Recorded Direction Of Travel EASTBOUND With E	A CLASS	tions Issued Crash Tire Mark Inction IAL FUNC trol ROL ature	1	Total Trai 0 Speed Lir	TRUCK Operating A lers mit Emergency NOT APPI Traffic Cont NO	Total Haz 0 Total Lan 2 Motor Veh ICABLE	Mat Types es icle Use
10	Unit IN T Veh STF Tota 1 Insu YES Mos PAF Trafi Two Surf BLA Truc	Status (RANSIT icle Type RAIGHT TRUCK (INSEI Il Occs rance? S tHarmful Event: Collision N RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat	Train/Bus # Recorded Direction Of Travel EASTBOUND With E	A CLASS	tions Issued Crash Tire Mark Inction IAL FUNC trol ROL ature	1	Total Trai 0 Speed Lir	TRUCK Operating A lers mit Emergency NOT APPI Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh ICABLE	Mat Types es icle Use
LO	Unit IN T Veh STF Tota 1 Insu YES Mos PAF Trafi Two Surf BLA Truc	Status (RANSIT icle Type RAIGHT TRUCK (INSEI Il Occs rance? S tHarmful Event: Collision N RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat	Train/Bus # Recorded Direction Of Travel EASTBOUND With E	A CLASS	tions Issued Crash Tire Mark Inction IAL FUNC trol ROL ature	1	Total Trai 0 Speed Lir	TRUCK Operating A lers mit Emergency NOT APPI Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh ICABLE	Mat Types es icle Use
01	Unit IN T Vehi STF Tota 1 Insu YES Mos PAF Trafi TWO Suff BLA Truc TRU	Status (RANSIT icle Type RAIGHT TRUCK (INSEI Il Occs rance? S tHarmful Event: Collision N RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat	Train/Bus # Recorded Direction Of Travel EASTBOUND With E	A CLASS	tions Issued Crash Tire Mark Inction IAL FUNC trol ROL ature	1	Total Trai 0 Speed Lir	TRUCK Operating A lers mit Emergency NOT APPI Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh ICABLE	Mat Types es icle Use
01	Unit IN T Vehi STF Tota 1 Insu YES Mos PAF Trafi TWO Suff BLA Truc TRU	Status (RANSIT icle Type RAIGHT TRUCK (INSEI IOCcs rance? S tHarmful Event: Collision \ RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat JCK OR TRUCK COME	Train/Bus # Recorded Direction Of Travel EASTBOUND With E	A CLASS	tions Issued Mark IAL FUNC trol ROL ature T	1	Total Trai 0 Speed Lir	TRUCK Operating A lers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL	Total Haz 0 Total Lan 2 Motor Veh ICABLE rol Inopera	Mat Types es icle Use
10	Unit IN T Vehi STF Tota 1 Insu YES Mos PAF Trafi TWO Suff BLA Truc TRU	Status (RANSIT icle Type RAIGHT TRUCK (INSEI I Occs rance? S t Harmful Event: Collision \ RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat JCK OR TRUCK COME Vehicle	Train/Bus # Recorded Direction Of Travel EASTBOUND With E	A CLASS	tions Issued Mark IAL FUNC trol ROL ature T	TION	Total Trai 0 Speed Lir 25	TRUCK Operating A lers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL	Total Haz 0 Total Lan 2 Motor Veh ICABLE rol Inopera	Mat Types es icle Use
	Unit IN T Veh STF Tota 1 Insu YES PAR Trafi Two Surf Trafi Truc TRU	Status (RANSIT icle Type RAIGHT TRUCK (INSEI I Occs rance? S t Harmful Event: Collision N RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat JCK OR TRUCK COME Vehicle License Plate Number	Train/Bus # Recorded Direction Of Travel EASTBOUND With E	A CLASS	tions Issued Mark IAL FUNC trol ROL ature T	TION	Total Trai 0 Speed Lir 25 St WI	TRUCK Operating A Operating A Iters mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is: UNITED S1	Total Haz 0 Total Lan 2 Motor Veh ICABLE rol Inopera	Mat Types es icle Use
ONIT 01	Unit IN T Vehi STF Tota 1 Insu YES Mos PAF Trafi TWO Suff BLA Truc TRU	Status (RANSIT icle Type RAIGHT TRUCK (INSEI ICCCS rance? S tHarmful Event: Collision N RKED MOTOR VEHICL fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat JCK OR TRUCK COME Vehicle License Plate Number C15358	Train/Bus # Recorded Direction Of Travel EASTBOUND With E S) BINATION > 10,000LBS G	A CLASS	tions Issued Mark ICTION IAL FUNC trol ROL ature T	TION	Total Trai 0 Speed Lir 25 St WI Year	TRUCK Operating A Operating A Iters mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is: UNITED S1 Model	Total Haz 0 Total Lan 2 Motor Veh ICABLE rol Inopera	Mat Types es icle Use
UNII 01	Unit IN T Veh STF Tota 1 Insu YES PAR Trafi Two Surf Trafi Truc TRU	Status (RANSIT icle Type RAIGHT TRUCK (INSEI ICCCS rance? S tHarmful Event: Collision N RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS K Bus or HazMat JCK OR TRUCK COME Vehicle License Plate Number C15358 Vehicle Identification Nur 5VCACRAF5LC23162	Train/Bus # Recorded Direction Of Travel EASTBOUND With E S) BINATION > 10,000LBS G	A CLASS Total#Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH WWR/GCWR Plate Type MUN - MI Make AUTOCA	tions Issued Mark Inction IAL FUNC trol ROL ature T	TION	Total Trai 0 Speed Lir 25 St WI	TRUCK Operating A Operating A Iers MOT APPI Traffic Cont NO Road Grade LEVEL Country of Is: UNITED S1 Model TRUCK	Total Haz 0 Total Lan 2 Motor Veh ICABLE rol Inopera	Mat Types es icle Use
UNII 01	Unit IN T Veh STF Tota 1 Insu YES PAR Trafi Two Surf Trafi Truc TRU	Status TRANSIT icle Type RAIGHT TRUCK (INSEI I Occs rance? S tHarmful Event: Collision V RKED MOTOR VEHICL fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat JCK OR TRUCK COME Vehicle License Plate Number C15358 Vehicle Identification Nur	Train/Bus # Recorded Direction Of Travel EASTBOUND With E S) BINATION > 10,000LBS G	A CLASS Total#Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH WWR/GCWR Plate Type MUN - MI Make AUTOCA Body Style	tions Issued Mark Inction IAL FUNC trol ROL ature T	TION	Total Trai 0 Speed Lir 25 St WI Year	TRUCK Operating A Operating A Iters mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is: UNITED S1 Model	Total Haz 0 Total Lan 2 Motor Veh ICABLE rol Inopera	Mat Types es icle Use
UNIT 01	Unit IN T Veh STF Tota 1 Insu YES PAF Traff TWO Suff BLA Truc TRU	Status (RANSIT icle Type RAIGHT TRUCK (INSEI ICCCS rance? S tHarmful Event: Collision N RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS K Bus or HazMat JCK OR TRUCK COME Vehicle License Plate Number C15358 Vehicle Identification Nur 5VCACRAF5LC23162 Color WHI - WHITE	Train/Bus # Recorded Direction Of Travel EASTBOUND With E S) BINATION > 10,000LBS G	A CLASS Total#Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH VWR/GCWR Plate Type MUN - MI Make AUTOCA Body Style CB - CAE	CrashTire Mark Inction IAL FUNC trol ROL ature T	TION	Total Trai 0 Speed Lir 25 St WI Year	TRUCK Operating A Operating A Iers MOT APPI Traffic Cont NO Road Grade LEVEL Country of Is: UNITED S1 Model TRUCK	Total Haz 0 Total Lan 2 Motor Veh ICABLE rol Inopera	Mat Types es icle Use
01 UNIT 01	Unit IN T Veh STF Tota 1 Insu YES PAF Traff TWO Suff BLA Truc TRU	Status (RANSIT icle Type RAIGHT TRUCK (INSEI ICCcs rance? S tHarmful Event: Collision N RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS K Bus or HazMat JCK OR TRUCK COME License Plate Number C15358 Vehicle Identification Nur 5VCACRAF5LC23162 Color WHI - WHITE Initial Contact Point	Train/Bus # Recorded Direction Of Travel EASTBOUND With E S) BINATION > 10,000LBS G1 mber 29	A CLASS Total#Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH WWR/GCWR Plate Type MUN - MI Make AUTOCA Body Style	CrashTire Mark Inction IAL FUNC trol ROL ature T	TION	Total Trai 0 Speed Lir 25 St WI Year	TRUCK Operating A Operating A Iers MOT APPI Traffic Cont NO Road Grade LEVEL Country of Is: UNITED S1 Model TRUCK	Total Haz 0 Total Lan 2 Motor Veh ICABLE rol Inopera	Mat Types es icle Use
01 UNIT 01	Unit IN T Veh STF Tota 1 Insu YES PAF Traff TWO Suff BLA Truc TRU	Status (RANSIT icle Type RAIGHT TRUCK (INSEI IOCcs rance? S Harmful Event: Collision N RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS K Bus or HazMat JCK OR TRUCK COME Vehicle License Plate Number C15358 Vehicle Identification Nur SVCACRAF5LC23162 Color WHI - WHITE Initial Contact Point 03 - RIGHT SIDE MID	Train/Bus # Recorded Direction Of Travel EASTBOUND With E S) BINATION > 10,000LBS G1 mber 29	A CLASS Total#Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curve STRAIGH VWR/GCWR Plate Type MUN - MI Make AUTOCA Body Style CB - CAE Vehicle Da	tions Issued Mark Inction IAL FUNC trol ROL ature T UNICIPAL R B CHASSIS image	TION	Total Trai 0 Speed Lir 25 St WI Year	TRUCK Operating A Operating A Iers MOT APPI Traffic Cont NO Road Grade LEVEL Country of Is: UNITED S1 Model TRUCK	Total Haz 0 Total Lan 2 Motor Veh ICABLE rol Inopera	Mat Types es icle Use tive/Missing
UNIT 01 UNIT 01	Unit IN T Veh STF Tota 1 Insu YES PAF Traf TWO Suff BLA Truc TRU	Status (RANSIT icle Type RAIGHT TRUCK (INSEI ICCcs rance? S tHarmful Event: Collision N RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS K Bus or HazMat JCK OR TRUCK COME License Plate Number C15358 Vehicle Identification Nur 5VCACRAF5LC23162 Color WHI - WHITE Initial Contact Point	Train/Bus # Recorded Direction Of Travel EASTBOUND With E S) BINATION > 10,000LBS G1 mber 29	A CLASS Total#Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curve STRAIGH VWR/GCWR Plate Type MUN - MI Make AUTOCA Body Style CB - CAE Vehicle Da	CrashTire Mark Inction IAL FUNC trol ROL ature T	TION	Total Trai 0 Speed Lir 25 St WI Year	TRUCK Operating A Operating A Iers MOT APPI Traffic Cont NO Road Grade LEVEL Country of Is: UNITED S1 Model TRUCK	Total Haz 0 Total Lan 2 Motor Veh ICABLE rol Inopera	Mat Types es icle Use tive/Missing

G7L0FQBC6T

C22-16329

, .

× .

WISCONSIN MOTOR VEHICLE CRASH REPORT

SHEBOYGAN POLICE DEPARTMENT 1315 N 23RD ST SHEBOYGAN, WI 53081 (920) 459-3333

	_			1				
		Towed Due To Damage			le Removed By			
		NOT TOWED		OPER	RATOR			
		What Driver Was Doing		Vehic	le Factors			
		GOING STRAIGHT						
		Driver Prior Action Other		OTHE	ER DISABLED			
		Driver Actions						
	щ	NO CONTRIBUTING ACTI	ON					
E	U							
UNIT	VEHICLE							
-	m							
	-							
		OwnerName		0	OwnerAddress			
		SHEBOYGAN CITY			28 CENTER AVE # 110			
01	01	(920) 459-4000		S	HEBOYGAN, WI 53081 , US			
		Sequence Of Events						
		Event						
	01	MOTOR VEH IN TRANSPO	DRT					
	N	Event						
	02	EQUIPMENT FAILURE (BI	LOWN TIRE, BRAKE FAI	ILURE,	ETC)			
	03	Event	-					
	0	PARKED MOTOR VEHICL	E					
	04	Event						
	0							
		Policy Holder						
UNIT		Insurance Company		Go	vernment			
		CITIES-&-VILLAGES-MUT	UAL-INS-CO	SHEBOYGAN CITY				
		Individual		Sec. and				
		Driver		Cita	ations Issued	Sex		
		MARK A POLICH		0		MALE		
	AL	(920) 905-0419		Dat	te of Birth	Race		
F	B				/14/1979	WHITE		
LINU	INDIVIDUAL	Address			ver License Number			
2	9	2709 PERSHING AVE			205417945405			
	-	SHEBOYGAN, WI 53083 ,	US	51	ATE: WISCONSIN COUNTRY: UNI	TED STATES		
	0-	On Duty	Crash	Saf	fety Equipment			
		fety Equipment						
1		Row	Seat Position	SH	OULDER & LAP BELT			
		01 - FRONT ROW	09 - RIGHT					
		HelmetUse		Hel	ImetCompliance			
		Eye Protection		Tin	tCompliance			
	-	Injury Se	verity	Air	bag			
01	001		PARENT INJURY		N DEPLOYED			
		Ejected	Ejection Path			Trapped/Extricated		
		NOT EJECTED	NOT EJECTED/NOT AP	PLICA	BLE	NOT TRAPPED		
		Medical Transport		EM	IS Agency Identifier	EMS Run#		
		NOT TRANSPORTED			5 ,			
		Hospital	and the second	Dat	te of Death	Time of Death		
		Distracted D	ed By Source					
		Distracted By NOT A	PPLICABLE (NOT DISTR	ACTE	D)			
		Distracted By Action NOT DISTRACTED						
		NOT DISTRACTED						

G7L0FQBC6T C22-16329

5.

ï

WISCONSIN MOTOR VEHICLE CRASH REPORT

SHEBOYGAN POLICE DEPARTMENT 1315 N 23RD ST SHEBOYGAN, WI 53081 (920) 459-3333

		Non Motorist	ing Unit#	Location							
		Prior Action		-L							
UNIT	INDIVIDUAL	Action									
		Action Other									To/From School
	1	Drug & Alcohol NO	pected Alcohol (Jse	Suspe NO	cted Drug Use					1
		Alcohol Test Given		Alcohol Test T	ype				Alcohol Tes	tResults	
		Drug Test Given TEST NOT GIVEN		Drug Test Typ	9		Drug	TestResu	lts		
01	001	Drug Type									
		Individual Condition									
		APPEARED NORMAL									
		Carrier				Source					
			le Owner Sar	ne as Carrier		DRIVER					
01	01	SHEBOYGAN CIT	Y			Address 828 CENTER AVE # 110 SHEBOYGAN, WI 53081 , US					
	BUS	GVWR 10,001-26,000 LBS		onfiguration	(2-AXLE		ORE T		rgo Body Type RBAGE/REF	USE	
UNIT		US DOT #	Carrier Ty		Permitted Load						
	TRUCK	OS/OW Load	ermitNumber	Pe	rmitted Ve		Es	cort Vel	nicle Require	d	scort Vehicle Present
	F	Measured Height	Measu	ared Length	Permitted	Route Measured Wid	th		Permit Measured W		Scort venicle riesent
I	Uni	t Summary									
	Unit	Status			Vehicle Op	perating As Clas	sification		UnitType		
02	Vehi	cle Type			DCLASS	>			Operating A		nents
		SENGER CAR	Train/Bus#Re	corded	Total#Citi	ations Issued		Total Tra	ilers	TotalHaz	Aat Types
	Insu	rance?	Direction Of Tr	avel		CrashTire		0 Speed L	imit	0 Total Lane	s
UNIT	YES Mos	t Harmful Event: Collision Wi	UNKNOWN th		Special Fu			25	Emergency	2 Motor Vehic	cle Use
		TOR VEH IN TRANSPOR	रा		NO SPEC	CIAL FUNCTIO	ON		NOT APPI Traffic Cont	ICABLE	
	TWO	O-WAY, NOT DIVIDED			NO CON	TROL			NO	•	vennissing
		ace Type CKTOP (BITUMINOUS)			Road Curves				Road Grade		

G7L0FQBC6T

C22-16329

1.

-

WISCONSIN MOTOR VEHICLE CRASH REPORT

	Truc NO	k Bus or HazMat						
-	-	Vehicle						Contraction of the second
		License Plate Nu	mber		te Type	St	Country of Issuance	
		ALB8795	- 11 - 1	Ma	T - AUTOMOBILE	WI Year	UNITED STATES	
02	02	Vehicle Identification Number 1FAFP34N35W209496			RD	2005	Model FOCUS	
		Color			dy Style		Bus Use	
		BLU - BLUE			- SEDAN			
	Щ	Initial Contact Poi		Ve	hicle Damage			7 8 9 10 11
UNIT	Ę	07 - LEFT REA		SIDE REAR	6 12			
	VEHICLE	MINOR DAMAG				1,00 11	CID L HLPHI	54321
	-	Towed Due To Da	amage		hicle Removed By VNER			
		What Driver Was		Ve	hicle Factors			
		Driver Prior Action		NC	T APPLICABLE			
UNIT	VEHICLE	Driver Actions NO CONTRIBU	ITING ACTION					
02	02	OwnerName CRISTY LYNN (920) 362-3664			OwnerAddress 1521 KAUFMANN AV SHEBOYGAN, WI 530			
	10	Sequence O	fEvents					
	01	Event PARKED MOT						
	02	Event MOTOR VEH II	N TRANSPORT					
	03	Event						
	04	Event			ner finn af en an feranden. Maar hen an genanden in die her verkenden sind gehaar en daaren		Ne de anno mart de las caleur parten de la prés la françois que	
F		Policy Holde	r					
UNIT		Insurance Compa	GENERAL-INS-CO		Individual CRISTY MURRAY			
	Pro	perty Owne	r David and the second s	dentes de				
PROP OWNER 01		^{vidual} STY LYNN MUR	RAY		Idress 21 KAUFMANN AVE HEBOYGAN, WI 53081	, US		
		ed Objects S	truck	-				
	01	Striking Unit 02	Struck Object OTHER FIXED OBJECT				Structure Number	Damage Tag Number



·

DEAN'S AUTO BODY, INC.

Workfile ID: PartsShare: 018fa2f1 6Zz5VZ

Deans Has the Means for All Your Collision Needs! 1407 N 29TH ST, SHEBOYGAN, WI 53081 Phone: (920) 457-5494 FAX: (920) 457-6495

Preliminary Estimate

Custon	ner: Murray, Crist	У				
			Written By: Jo	be Black		
Insured:	Murray, Cristy	Policy #:		Cla	im #:	
Type of Loss: Date of Loss:				Da	ys to Repair:	0
Point of I	mpact: 07 Left Rear					
Owner:		Inspectio	In	surance Con	ipany:	
Murray, C	Cristy	DEAN'S AU	TO BODY, INC.			
1521 Kau	ıfmann Ave	1407 N 297	TH ST			
Sheboyga	an, WI 53081	SHEBOYGA	N, WI 53081			
(920) 362	2-3664 Cell	Repair Faci	lity			
		(920) 457-	5494 Business			
			VEHIC	1 F		
			VEHIC	in in		
2005 FOR	RD Focus SE ZX4 4D SED	9 4-2.0L Gasoline SMPI Blue	VEHIC			
2005 FOR VIN:	RD Focus SE ZX4 4D SEC 1FAFP34N35W209496	9 4-2.0L Gasoline SMPI Blue Interior Color:	VENIC	Mileage In:	162,906	Vehicle Out:
	1FAFP34N35W209496		Blue		162,906	Vehicle Out:
VIN:	1FAFP34N35W209496	Interior Color:		Mileage In:	162,906 Poor	Vehicle Out: Job #:
VIN: License: State:	1FAFP34N35W209496 ALB-8795 WI	Interior Color: Exterior Color: Production Date:	Blue	Mileage In: Mileage Out: Condition:		Job #:
VIN: License: State: TRA	1FAFP34N35W209496 ALB-8795	Interior Color: Exterior Color:	Blue	Mileage In: Mileage Out:		Job #: Passenger Air Bag
VIN: License: State: TRA	1FAFP34N35W209496 ALB-8795 WI ANSMISSION erdrive	Interior Color: Exterior Color: Production Date: DECOR	Blue	Mileage In: Mileage Out: Condition: Keyless Entry		Job #: Passenger Air Bag SEATS
VIN: License: State: TRA Ove 5 S	1FAFP34N35W209496 ALB-8795 WI ANSMISSION	Interior Color: Exterior Color: Production Date: DECOR Dual Mirrors Tinted Glass	Blue	Mileage In: Mileage Out: Condition: Keyless Entry RADIO		Job #: Passenger Air Bag SEATS Cloth Seats
VIN: License: State: TRA Ove 5 S PO	1FAFP34N35W209496 ALB-8795 WI ANSMISSION erdrive speed Transmission	Interior Color: Exterior Color: Production Date: DECOR Dual Mirrors	Blue 10/2004	Mileage In: Mileage Out: Condition: Keyless Entry RADIO AM Radio		Job #: Passenger Air Bag SEATS
VIN: License: State: TR/ Ove 5 S PO Pov	1FAFP34N35W209496 ALB-8795 WI ANSMISSION erdrive speed Transmission WER	Interior Color: Exterior Color: Production Date: DECOR Dual Mirrors Tinted Glass Console/Storage	Blue 10/2004	Mileage In: Mileage Out: Condition: Keyless Entry RADIO AM Radio FM Radio Stereo		Job #: Passenger Air Bag SEATS Cloth Seats Bucket Seats WHEELS
VIN: License: State: TRA Ove 5 S POV Pov Pov	1FAFP34N35W209496 ALB-8795 WI ANSMISSION erdrive speed Transmission WER wer Steering	Interior Color: Exterior Color: Production Date: DECOR Dual Mirrors Tinted Glass Console/Storage Overhead Consol	Blue 10/2004	Mileage In: Mileage Out: Condition: Keyless Entry RADIO AM Radio FM Radio Stereo Search/Seek		Job #: Passenger Air Bag SEATS Cloth Seats Bucket Seats
VIN: License: State: TRJ Ove 5 S PO Pov Pov Pov	1FAFP34N35W209496 ALB-8795 WI ANSMISSION erdrive speed Transmission WER wer Steering wer Brakes	Interior Color: Exterior Color: Production Date: DECOR Dual Mirrors Tinted Glass Console/Storage Overhead Consol CONVENIENCE	Blue 10/2004 e	Mileage In: Mileage Out: Condition: Keyless Entry RADIO AM Radio FM Radio Stereo		Job #: Passenger Air Bag SEATS Cloth Seats Bucket Seats WHEELS Wheel Covers

,

i

*

2005 FORD Focus SE ZX4 4D SED 4-2.0L Gasoline SMPI Blue

Line	Ope	er	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	REAR BUMPER							
2	Rep		mper cover hte: CCC Guide to Estimating G36	6S4Z17K835BA	1	417.92	1.5	2.8
			ny Component clear coated as a ar coat mix because of flex addit					erent
3		Ad	d for Clear Coat					1.1
4	MISCELLANEOUS	OPER/	ATIONS					
5	# Rep	pl Ad	ministration Supplies		1	25.00		
6	#	Ha	zardous waste removal		1	6.00	т	
7	# Rep	pl Fle	ex additive		1	6.50	т	
				SUBTOTALS		455.42	1.5	3.9

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				442.92
Body Labor	1.5 hrs	@	\$ 68.00 /hr	102.00
Paint Labor	3.9 hrs	@	\$ 68.00 /hr	265.20
Paint Supplies	3.9 hrs	@	\$ 45.00 /hr	175.50
Body Supplies	1.5 hrs	@	\$ 5.00 /hr	7.50
Miscellaneous				12.50
Subtotal				1,005.62
Sales Tax	\$ 1,005.62	@	5.5000 %	55.31
Grand Total				1,060.93
Deductible				0.00
CUSTOMER PAY				0.00
INSURANCE PAY				1,060.93

MyPriceLink Estimate ID / Quote ID: 1009540312516796416 / 113073047

-

2005 FORD Focus SE ZX4 4D SED 4-2.0L Gasoline SMPI Blue

As a family owned business, OUR MISSION, is to be your #1 collision repair facility. To provide you with outstanding customer care as we honestly and ethically repair your vehicle using environmentally friendly materials, the latest techniques, and up-to-date procedures. We will strive to grow our company with integrity to keep your business for life.

** All supplements must be addressed before the vehicle leaves. Any supplements left open will result in the vehicle not being delivered until the supplement is agreed upon with a copy in hand.

Per Wisconsin Statue 628.46 - any claim not paid within 30 days is subject to a 7.5% interest charge.

TOTAL LOSS ESTIMATES

Charges for total loss estimates with pictures and documentation to support estimate

Minimum of 4 hours at \$90 and going up from there depending what is all need to complete the written evaluation for a total loss.

Disassembly to gain access to document damage will be added on accordingly at the proper shop rate.

Scanning and measuring for diagnosing complete damage, will be billed out for each job accordingly at the proper shop rate.

Any OEM repair procedures needing a subscription to gather information for the repairs will also be added per vehicle according.

STORAGE CHARGES are \$50 per day

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

2005 FORD Focus SE ZX4 4D SED 4-2.0L Gasoline SMPI Blue

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DE2JK00, CCC Data Date 09/16/2022, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2023 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

1, S.

2005 FORD Focus SE ZX4 4D SED 4-2.0L Gasoline SMPI Blue

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
2	Broadway Ford Hyundai Genesis	#6S4Z17K835BA	\$ 417.92
	1010 S Military Ave	Bumper cover	
	Green Bay WI 54304	Quote: 1338263642	
		Expires: 11/11/22	

. . .

2005 FORD Focus SE ZX4 4D SED 4-2.0L Gasoline SMPI Blue

ALTERNATE PARTS USAGE

2005 FORD Focus SE ZX4 4D SED 4-2.0L Gasoline SMPI Blue

VIN:	1FAFP34N35W209496	Interior Color:		Mileage In:	162,906	Vehicle Out:
License:	ALB-8795	Exterior Color:	Blue	Mileage Out:		
State:	WI	Production Date:	10/2004	Condition:	Poor	Job #:

Alternate Part Type	Selection Method	# Of Times Notified Of Available Parts	# Of Parts Selected	
Aftermarket Automatically List		0	0	
Optional OEM	Automatically List	0	0	
econditioned Automatically List		0	0	
Recycled N/A		0	0	

DEAN'S AUTO BODY, INC. 1407 N 29TH ST, SHEBOYGAN, WI 53081 Phone: (920) 457-5494, Fax: (920) 457-6495

Image Report							
Owner:	Murray, Cristy	Insurance:		Estimator:	Joe Black	Vehicle Out:	
RO Number		Claim Number:					
Year:	2005	Color:	Blue	License Plate:	ALB-8795	Production Date:	10/2004
Make:	FORD	Body Style:	4D SED	State:	WI	Mileage In:	162,906
Model:	Focus SE ZX4	Engine:	4-2.0L Gasoline S	VIN:	1FAFP34N35W209496	Condition:	Poor



10/12/2022 Comments:

÷ .



10/12/2022 Comments:



10/12/2022 Comments:



10/12/2022 Comments:



10/12/2022 Comments:



10/12/2022 Comments:

DEAN'S AUTO BODY, INC. 1407 N 29TH ST, SHEBOYGAN, WI 53081 Phone: (920) 457-5494, Fax: (920) 457-6495

Image Report							
Owner:	Murray, Cristy	Insurance:		Estimator:	Joe Black	Vehicle Out:	
RO Number:		Claim Number:					
Year:	2005	Color:	Blue	License Plate:	ALB-8795	Production Date:	10/2004
Make:	FORD	Body Style:	4D SED	State:	WI	Mileage In:	162,906
Model:	Focus SE ZX4	Engine:	4-2.0L Gasoline S	VIN:	1FAFP34N35W209496	Condition:	Poor



10/12/2022 Comments:

 \overline{r}^{-}

, ÷.



10/12/2022 Comments:



10/12/2022 Comments:



10/12/2022 Comments:



10/12/2022 Comments:



10/12/2022 Comments:

DEAN'S AUTO BODY, INC. 1407 N 29TH ST, SHEBOYGAN, WI 53081 Phone: (920) 457-5494, Fax: (920) 457-6495

Image Report							
Owner:	Murray, Cristy	Insurance:		Estimator:	Joe Black	Vehicle Out:	
RO Number:		Claim Number:					
Year:	2005	Color:	Blue	License Plate:	ALB-8795	Production Date:	10/2004
Make:	FORD	Body Style:	4D SED	State:	WI	Mileage In:	162,906
Model:	Focus SE ZX4	Engine:	4-2.0L Gasoline S	VIN:	1FAFP34N35W209496	Condition:	Poor



10/12/2022 Comments:

ĩ

Ξ.



10/12/2022 Comments:



10/12/2022 Comments:



10/12/2022 Comments:



10/12/2022 Comments: