CERTIFICATE OF SUBSTANTIAL COMPLETION

| Owner: | City of Sidney | _Owner's Contract No.: | WR2300047 | | |
|--|--|---------------------------|-----------|--|--|
| Engineer: | Interstate Engineering, Inc. | _Engineer's Project No.: | WR2300047 | | |
| Contractor: Western Municipal Construction | | Contractor's Project No.: | | | |
| Project: | North Park Elevated Water Tower Replacement (Phase 1) | | | | |
| Contract No | Contract Name: Schedule 1 and Schedule 2 | | | | |
| | | | | | |
| This 🛛 Pre | liminary 🛛 Final Certificate of Substantial Completion | on applies to: | | | |
| All Worl | • The following specified portions of the Work: | | | | |

Schedule 1

Date of Substantial Completion: July 2, 2025

The Work to which this Certificate applies has been inspected by authorized representatives of Owner, Contractor, and Engineer, and found to be substantially complete. The Date of Substantial Completion of the Work or portion thereof designated above is hereby established, subject to the provisions of the Contract pertaining to Substantial Completion. The date of Substantial Completion in the final Certificate of Substantial Completion marks the commencement of the contractual correction period and applicable warranties required by the Contract.

A punchlist of items to be completed or corrected is attached to this Certificate. This list may not be all-inclusive, and the failure to include any items on such list does not alter the responsibility of the Contractor to complete all Work in accordance with the Contract Documents.

Amendments of contractual responsibilities recorded in this Certificate should be the product of mutual agreement of Owner and Contractor; see Paragraph 15.03.D of the General Conditions.

The responsibilities between Owner and Contractor for security, operation, safety, maintenance, heat, utilities, insurance, and warranties upon Owner's use or occupancy of the Work shall be as provided in the Contract, except as amended as follows:

| Amendments to Owner's responsibilities: | ☐ None | As follows |
|--|--------|-------------|
| Amendments to Contractor's responsibilities: | ☐ None | As follows: |

The following documents are attached to and made a part of this Certificate:

WMC Request for Substantial Completion Dated: 07/02/2025

Schedule 1 Punchlist Dated: 07/02/2025

This Certificate does not constitute an acceptance of Work not in accordance with the Contract Documents, nor is it a release of Contractor's obligation to complete the Work in accordance with the Contract Documents.

| | ENGINEER; | OWNER: | CONTRACTOR: |
|-------|------------------|---|-------------|
| By: | Mara | _ Ву | Ву |
| Name: | Jordan Mayer | Name: | Name: |
| Title | Project Engineer | Title | _ Title |
| | | EJCDC [®] C-625, Certificate of Substantial Completion | |

Copyright[©] 2018 National Society of Professional Engineers, American Council of Engineering Companies, and American Society of Civil Engineers. All rights reserved.



July, 2, 2024

Mr. Jordan Mayer

Subject: Sidney North Park Elevated Water Tower Replacement Phase 1

Jordan,

Western Municipal Construction Inc has completed the above referenced project (Schedule 1) in accordance with the contract plans, specifications, and agreement; therefore Western Municipal Construction is Requesting a Certificate of Substantial Completion on the Project for July 2, 025.

Your prompt attention to this request is greatly appreciated.

Please contact me if you have any questions.

Best Regards,

Dillon Clause

Dillon Clause

Project Manager



| PUNCHLIST ITEMS | | INTERSTATE |
|---------------------------------------|--|---------------------|
| PROJECT: North Park Elevated Tower Re | | placement – Phase 1 |
| CONTRACT: WR23-00-047 | | |
| DATE: July 2, 2025 | | |
| | | |

TO BE COMPLETED

1. Concrete work to be completed

- a._____Sidewalk / Driveway
 - i.— Driveway at 405 3rd St
 - ii. Private sidewalk at 415 3rd St.
 - iii.—Sidewalk and match to curb at 516 3rd St.

b. Curb and Gutter

- i. Southwestern corner of 3rd St. And 5th Ave.
 - 1. Little water in trench; verify with Badger
- ii. 610 3rd St NE: IE to confirm limits 7/2/2025 with Badger

c. Caulk expansion joints

| Status: | Complete 🗆 | Not Complete | In Progress | \boxtimes |
|---------|------------|--------------|-------------|-------------|
| | | | | |

Notes: 610 3rd St NE curb not replaced per Property Owner. Prefer to wait until curb is replaced across the street and before the City overlays 3rd St NE. Cones will be removed after 7 days.

2.—Complete grass restoration for the Project and verify that:

- a. Restore Park on the northern side
- b. Repair private property damage (IE to provide pre/post pictures wk of 6/23/25)
- c: Areas are furnished with fresh topsoil material
- d. Areas are raked and free of rock and gravel
- e.—Areas are hydro-seeded and watered
- f. Clean fire hydrants from hydroseed
- g. High spot at 424 3rd St SE; WMC to check with Property Owner and regrade if necc.
- h. Seeding at 415 3rd St after concrete sidewalk poured

| Status: | Complete 🛛 | Not Complete 🛛 | In Progress 🛛 |
|---------|--|----------------------|---------------|
| Notes: | 415 3 rd St wanted to seed th | eir yard themselves. | |

3. Complete submittals

- a. Concrete, Asphalt, Hydroseed
- b. BABA Certification for hydrant extension

| Status: | Complete 🗆 | Not Complete 🛛 | In Progress | \boxtimes |
|---------|------------|----------------|-------------|-------------|
| Notes: | | | | |

4. Cleanup

| 4. | Cleund | γp | | | | |
|----------|-----------------|---|---|---------------------------------------|---|--|
| | a. - | Remove c | ind clean up gravel on back sid | le of curb and gutter alc | ong entire length of Project | |
| | | and side s | streets | | | |
| | b. | -Remove r | ock in park, south of hydrant @ |) STA 326 08 | | |
| | c. – | <u>–Remove unwanted traffic control signage</u> | | | | |
| | d. | Clear dirt | from streets, valley gutters, exte | erior intersections, and t | emp water road crossings | |
| | | i. C | ity of Sidney to sweep streets; $ mathbb{V}$ | VMC to sweep curbs, sid | lewalk, and driveways | |
| | | ii. —Pl | ace excess base course from te | mp water road crossing | s in affected alleys. Refer | |
| | | ŧe | - 6/18/25 Mtg Mins | | | |
| | | iii.—Re | epair temp water driveway cros : | sings in alleys | | |
| | e. - | -Repair as | phalt damage (IE to provided p | re/post pictures wk of 6 , | /25/25) | |
| | f. — | -Staging a | rea(s) | | | |
| | g. | Remove e | quipment, porta potty; traffic co | ontrol | | |
| | | i.—C | ity will sweep streets under equi | i pment; WMC to clean a | curbs and sidewalks | |
| | | Status: | Complete 🗆 | Not Complete 🛛 | In Progress 🛛 | |
| | | Notes: | · | 1 | 0 | |
| | | 140165. | some equipment to city lot in | | | |
| 5 | Asphal | t navemen | Frestoration | | | |
| 0. | | | 0250618 Asphalt Paving Limits | andfemailed on 6/23/2 | 25 | |
| | u. | | ozoooro_rophan raving Linns | | | |
| | | Status: | Complete 🛛 | Not Complete 🛛 | In Progress 🛛 | |
| | | Notes: | | | _ | |
| | | | | | | |
| <u> </u> | Final | urh eton/h | ox elevation verification w/ City | | | |
| 0. | | | , can access and operate all cu | | | |
| | а. | 1 1 | 18 3 rd St SE: Raise to 1"-2" bel | | | |
| | | | 15 3rd St SE: Lower to 1-2" bel | | | |
| | | | I curb stops to be checked and | | vel to 2" below the | |
| | | | inface | | | |
| | | | | | | |
| | | Status: | Complete 🛛 | Not Complete 🛛 | In Progress 🛛 | |
| | | Notes: | | | | |
| | | | | | | |

7. Verify City can access and operate all gate values pre and post asphalt paving
 a. Three (3) value boxes were noticed preliminarily; refer to 6/18/25 Mtg Mins

| | Status: <u>Notes:</u> | Complete 🛛 See Warranty Items | Not Complete 🛛 | In Progress 🛛 |
|--|--|--|---------------------------|-----------------------|
| 8.—Check | continuity (| of tracer wire for entire project | | |
| | Status: <u>Notes:</u> | Complete 🛛 Performed by City of Sidney | Not Complete 🛛 | In Progress 🛛 |
| 9.—Replac | e street sig i | n at 3 rd St NE / 5 th Ave NE; verif | y with City on location 8 | mounting requirements |
| | Status: <u>Notes:</u> | Complete 🛛 | Not Complete 🛛 | In Progress 🛛 |
| a. b. c. d. e. f. g. | 6"x 2" ni 2" curb si 2" street 6 6"x 2" ta 2" nipple Curb box 2 – 1" val | top 90° | | |
| | Notes: | WMC can send parts/pieces t | o NWP and City can pic | k up |

11. Warranty Items

i.

a. Water between asphalt paving lifts (402 3^{rd} St SE) \rightarrow IE to keep an eye on it



b. Asphalt pumping (524 3^{rd} St SE) \rightarrow IE to keep an eye on it



c. Asphalt damage (3rd St SE / 4th Ave SE) → IE to coordinate w/ City if repair is needed prior to Schedule 2 starting.



- d. Seeding verification in fall 2025
- e. Gate Valve Box at 3rd St / 5th Ave (STA 523+81, Sht CU 2.05) to be reset at start of Schedule 2 work
- f. MDU to replace light pole at 3rd St / 6th Ave: IE to contact MDU once streets are open back up to the public

| Status: | Complete 🛛 | Not Complete 🛛 | In Progress 🛛 |
|---------|------------|----------------|---------------|
| Notes: | | | |
| | | | |
| | | | |

12. Closeout Documents: Schedule 1

a. Certified Payrolls

i.

b. Request for Substantial Completion

i.—After completion of concrete restoration

| Status: | Complete 🛛 | Not Complete 🛛 | In Progress 🛛 |
|---------|------------|----------------|---------------|
| Notes: | | | |
| | | | |
| | | | |