

**Schedule of Photographs of Theo Bauer Building
Stephenville, Texas**

| Photograph Exhibit No. | Description |
|-------------------------------|---|
| 1 | Back wall of building |
| 2 | Back wall and area of land behind building |
| 3 | Back wall of building |
| 4 | Back door of building and added equipment room |
| 5 | Interior room of first floor (existing beauty salon) |
| 6 | Interior room of first floor (existing beauty salon) |
| 7 | Steel vault storage room |
| 8 | Interior room of first floor (existing beauty salon) |
| 9 | Interior room of midlevel floor (existing beauty salon) |
| 10 | Interior room of midlevel floor (existing beauty salon) |
| 11 | Bathroom on first floor |
| 12 | Bathroom on first floor |
| 13 | Hall area first floor |
| 14 | Back interior room of first floor (existing beauty salon) |
| 15 | Interior room of midlevel floor (existing beauty salon) |
| 16 | Interior room of midlevel floor (existing beauty salon) |
| 17 | Interior room of midlevel floor (existing beauty salon) |
| 18 | Interior room of first floor (existing beauty salon) |
| 19 | Hallway door to second floor |
| 20 | Common area first floor and stairway to midlevel floor |
| 21 | Back door and back wall of building |
| 22 | Interior stairway to midlevel floor |
| 23 | Stairway from midlevel floor to second floor |
| 24 | Interior room second floor |
| 25 | View of Courthouse square from second floor |
| 26 | Air conditioning unit second floor |
| 27 | Front room second floor showing portion of old stairway remaining |
| 28 | Front room second floor |
| 29 | Front room second floor |
| 30 | Front room second floor from interior partition wall |
| 31 | Interior room second floor |
| 32 | Stairwell to midlevel floor from second level floor |
| 33 | Stairwell to midlevel floor from first floor |