

**Schedule of Photographs of Theo Bauer Building  
Stephenville, Texas**

<b>Photograph Exhibit No.</b>	<b>Description</b>
1	Back wall of building
2	Back wall and area of land behind building
3	Back wall of building
4	Back door of building and added equipment room
5	Interior room of first floor (existing beauty salon)
6	Interior room of first floor (existing beauty salon)
7	Steel vault storage room
8	Interior room of first floor (existing beauty salon)
9	Interior room of midlevel floor (existing beauty salon)
10	Interior room of midlevel floor (existing beauty salon)
11	Bathroom on first floor
12	Bathroom on first floor
13	Hall area first floor
14	Back interior room of first floor (existing beauty salon)
15	Interior room of midlevel floor (existing beauty salon)
16	Interior room of midlevel floor (existing beauty salon)
17	Interior room of midlevel floor (existing beauty salon)
18	Interior room of first floor (existing beauty salon)
19	Hallway door to second floor
20	Common area first floor and stairway to midlevel floor
21	Back door and back wall of building
22	Interior stairway to midlevel floor
23	Stairway from midlevel floor to second floor
24	Interior room second floor
25	View of Courthouse square from second floor
26	Air conditioning unit second floor
27	Front room second floor showing portion of old stairway remaining
28	Front room second floor
29	Front room second floor
30	Front room second floor from interior partition wall
31	Interior room second floor
32	Stairwell to midlevel floor from second level floor
33	Stairwell to midlevel floor from first floor