

Work Order Statement

Details of Work Order:

We received a call out for 1621 Milian Circle in regards to the water bill being higher then usual. After checking the water meter on location it was determined that she had a water leak on her side of the property. Mrs. Milian was advised to contact a plumber to have a look at her water lines. A few days later we received another call out to the same location. Mrs. Milian stated that she believes the leak is on the property next door to her house. After Mrs. Milian further explained that all three houses were built from the same line that broke off to each house we decided to try to fix the issue by added a separate water tap to Mrs. Milian's house in hopes that it fixed the problem. But a few weeks later we received another call from Mrs. Milian stated that her bill is still high. This time we switched out her water module on the water meter. We have been working extremely hard to address Mrs. Milian's complaints.



TERRENCE BELL