



# CITY OF SWEENEY

102 W. Ashley Wilson Rd. • PO Box 248 • Sweeny, Texas 77480 • P: (979) 548-3321

## Office of Public Works Update

### Work Orders:

Water- 48 Closed, 4 water leaks were repaired.

Sewer- 9 Closed, 3 lines were jetted out.

Streets- 4 Closed, 4 potholes repaired.

Gas- 10 Closed, 1 gas leak repaired

Drainage- 2 Closed.

Permits- 12 Closed.

### Major Equipment:

The Pecan lift station was sucked out and Pump 1 was put into auto. Pump 2 inlet flange is cracked not allowing the pump to create a vacuum. The generator Battery was replaced, and generator is working.

The San Bernard lift Station was sucked out and pumping better.

Fix clog in RAS pumps at Wastewater Plant and adjusted valves to RAS Equally from each clarifier to the racetrack.

Well #1,2,3, and 4 had BiCarbus injected into them on the 27<sup>th</sup> and 30<sup>th</sup> of May. The Wells looked significantly clearer after the injections and time for chemicals to react.

Generators were all checked and will be checked on a regular basis, only 2 had issues.

The Police Departments Generator has multiple alarms, and a contractor has been called to fix it.

Well 3 Generator works but the automatic switch is still down waiting on parts to fix it.

### Sidewalk Repair:

Multiple contractors have been contacted to bid on repairing the sidewalks no quotes have come in yet.