102 W. Ashley Wilson Rd. • PO Box 248 • Sweeny, Texas 77480 • P: (979) 548-3321

Office of Public Works Quarterly Report

Work Orders:

Water- 118 Closed, 39 water leaks were repaired.

Sewer- 21 Closed, lines were jetted out.

Streets- 20 Closed, 16 potholes repair.

Gas- 23 Closed, 5 gas leaks repaired

Permits- 34 Closed.

Drainage- 22 Closed.

Building Repairs:

Both outside A/C units at the community center were repaired.

Mini Split was installed in the meeting room at the community center.

Public works had the front door replaced.

Major Equipment:

Generators were all checked and functioning, well #3 is the only one that needs to be switched over manually.

Well #1,2,3, and 4 had BiCarbus injected into them on the 27th and 30th of May. The Wells looked significantly clearer after the injections and time for chemicals to react.

Powell lift station was redone and added to the SCATA system.

Wastewater plants have had multiple sections repaired. The biggest issue that is now a concern is the age and size of the pumps for the wet well.

All lift Stations are functioning and have had the wet wells cleaned out.

Vehicle Repair:



102 W. Ashley Wilson Rd. • PO Box 248 • Sweeny, Texas 77480 • P: (979) 548-3321

Unit #100 had an oil change done.

Unit #101 had an oil change done, breaks repaired, and inspection done

Unit #103 had tire replacement done

Unit #104 had brakes and electrical issues repaired

Unit #105 is being repaired as the power steering pump went out.