

Attachment C – Additional Trail Crack Repair without Overlay

Prosser Dam Road Trail, and SR 89 Trail



Map shows individual cracks along the Prosser Dam Road Trail and the SR 89 Trail. The Cracks proposed to be repair without an overlay.