



City of Tupelo

Jason L. Shelton
Mayor

Water and Light
Johnny Timmons, Director

August 21, 2020

COUNCIL

Markel Whittington
Ward One

Lynn Bryan
Ward Two

Travis Beard
Ward Three

Nettie Y. Davis
Ward Four

Buddy Palmer
Ward Five

Mike Bryan
Ward Six

Willie Jennings
Ward Seven

RE: Sewer line repair on Plant Road

On April 21, 2020, the Tupelo Water & Light Department discovered a deteriorated concrete sewer line under Plant Road. This sewer line is the primary transmission main for all of the city of Tupelo into central pumping station. Also, this deteriorated line caused erosion under the road and the road had begun to collapse. Since Plant Road is used daily by 18-wheelers as the primary entrance to the loading docks of Signify Corporation (Daybrite Lighting), this finding made it necessary to begin immediate repair/replacement of this line.

Upon excavation of the area by our sewer department, it was discovered that this line is sixteen feet deep. Therefore, we hired Paul Smithey Construction Company to replace 300 feet of 21" concrete sewer main with 24" pvc sewer main.

If you have any questions or need further information, please let me know.

Sincerely,

TUPELO WATER & LIGHT DEPARTMENT


Johnny Timmons
Manager



