

Existing Berliner Climber in the Murase Plaza Playground



Examples of needed maintenance in the near term.

Exposed metal on posts (high usage/age)



Rust starting near top of climber (age)



Braided cable exposed (high usage)

