

Public Art Maintenance Doc – Due Aug 7th, 2026

Artwork Name: Korean Wall / General MacArthur Sculpture

Location: Town Center Park

Date of inspection: August 7th

Name of inspector/ACHC member: Aaron Harris

1. Overall Condition to look for (Check the boxes if applicable and add any notes)

- ☒ Artwork looks stable and safe -
- ☐ No obvious damage or missing parts -
- ☐ No signs of vandalism or graffiti -
- ☐ Area around artwork is clean, maintained and accessible -
- ☐ Is there a plaque? If yes, what does it say -

Additional Comments:

Weather residue in around the wall could be cleaned but is probably cleaned by city seasonally. Lighting looked foggy but didn't inspect during night when lights were illuminated. MacArthur sculpture looked in great condition.

2. Structural / Safety Check (Look for anything that could make the artwork unsafe)

- ☒ No loose, cracked, or broken parts -
- ☐ Base/foundation appears solid -
- ☐ No sharp edges -
- ☐ No major leaning or movement -
- ☐ No trip hazards nearby -

Additional Comments:

3. Surface Condition (Check the visible surfaces)

- ☒ No heavy rust, corrosion, or rot -
- ☒ Paint/coating is in good condition -
- ☒ No major stains or discoloration -
- ☒ No peeling, bubbling, or flaking -
- ☒ No excessive dirt buildup, moss, etc -

Additional Comments:

4. Environment Around the Artwork

- ☒ Landscaping is maintained -
- ☒ Drainage looks adequate (no standing water) -
- ☒ Benches/signage nearby are in good shape -

Additional Comments:

5. Photos

Please take:

- One overall photo
- Photos of any damage or concerns
- Close-up photos if needed (i.e plaque)







Condition Rating

Choose one:

- ☒ Good — no action needed
- ☐ Fair — minor maintenance needed
- ☐ Poor — repair needed soon
- ☐ Critical — immediate attention required

Follow-Up Needed

- ☐ None
- ☒ Cleaning
- ☐ Graffiti removal
- ☐ Repair
- ☐ Safety review
- ☐ Further professional inspection

Additional Notes: