


April 18, 2025

Client: Silber Construction
Project: 9 Fieldcrest Drive
Location: Monsey, NY

On April 2nd, a representative from CATGO Materials Testing visited the project site to take a soil sample of the imported fill material. Material had been previously placed at the project site. CATGO representative excavated through the topsoil and sampled the imported fill at multiple locations to form a composite sample. The sample was then delivered to Phoenix Environmental Laboratories for analytical testing. See attached test results.

Gabriel J. O'Connell P.E.



goconnell@catgomt.com
845-656-3765