



**33 Astor Place
Village of Wesley Hills
Percolation/Deep Tests
March 22, 2022**

Test performed by Devin Crichlow, signed off by Rachel Barese, P.E.

Location 1

Deep Test:

0'-1.5' topsoil

1.5'-5' Brown/red silt/clay with stones 1" – 6"

Bedrock reached at 5'

No signs of groundwater

Location 2

Deep Test:

0'-1.5' topsoil

1.5'-9' Brown/red silt/clay with stones 1" – 6"

No signs of bedrock or groundwater

24" perc test at 5'

Run 1 – 55 minutes

Run 2 – 55 minutes

Run 3 – 55 minutes

Civil Tec Engineering & Surveying P.C.

139 Lafayette Avenue, 2nd Floor, Suffern, NY 10901 Tel 845.547.2241 Fax 845.547.2243

55 Brookside Avenue, Chester, NY 10918 Tel 845.610.3621

Civil-Tec.com

CIVILTEC

Engineering + Surveying



Civil Tec Engineering & Surveying P.C.

139 Lafayette Avenue, 2nd Floor, Suffern, NY 10901 Tel 845.547.2241 Fax 845.547.2243
55 Brookside Avenue, Chester, NY 10918 Tel 845.610.3621

Civil-Tec.com